### HAZARDOUS WASTE INSPECTION REPORT **GENERATORS -- SMALL QUANTITY GENERATORS**

Site Name Alumen Products Inc. ID Number PAPOY 9001697 Date 5/25/04 1 - No Violation Observed 2 - Not Applicable 3 - Not Determined

- 1	2 ·			REQUIREMENT	PA CIT. 25 PA Code	FED. CIT. 40 CFR	LINE NO.			
M				Hazardous waste determined all waste streams	262a.10	262.11	H001			
X				Identification Nt Authorized trans	262a.10	262.12	H002			
K				Authorized trans	262a.10	262.12(c)	H003			
W				Subsequent notii	262a.12(b)		H004			
K				Proper manifest ι	262a.10	262.21	H005			
Z	П			Manifests filled ou	262a.20		H006			
K	Ц			Manifests signed ευυρετίν	262a.23(a)	262.23	H007			
V				Generator waste accumulated on site for 90 days or less	262a.10	262.34(a)	H008			
	A			SQG waste accumulated on site for 180 days max unless 200 mile distance rule applies - 270 days	262a.10	262.34(e)(f)	H009			
	K			SQG waste accumulated on-site never exceeds 6000 kg	262a.10	262.34(e)(f)	H010			
				Satellite accumulation requirements complied with	262a.10	262.34(c)	H011			
A	9			Personnel training program per 265.16 complied with	262a.10	262.34(a)(4) 262.34(d)	H012			
X				Manifest exception and biennial reports retained for 3 years	262a.10	262.40(a)(b)	H013			
k	П			Specified records retained for three years	262a.10	262.40(c)	H014			
K	<u> </u>	Ц		Biennial reports submitted to the Department (LQG only)	262a.41	262.41	H015			
	9	9		Exception reporting procedures followed	262a.42	262.42	H016			
	Ц	Ц	Ц	Spill reporting procedures followed	262a.10	262.34(d)	H017			
Æ	Ц	Ц		PPC plan developed and implemented	262a.10	262.34(a)	H018			
4	Ц		Ч	Special requirements followed for international shipments	262a.10	262.50	H019			
	_		_			262.60				
		닐	닠	Source reduction strategy prepared and available (LQG only)	262a.100		H020			
4	4	4	븨	Excluded waste complies with exclusionary requirements	261a.4	261.4	H021			
$\vdash$	-	-	_							
$\vdash$	4	-	-	·						
$\vdash$	-	-	-		·					
$\vdash \vdash$	$\dashv$	+	-							

Page		of	
------	--	----	--

# HAZARDOUS WASTE INSPECTION REPORT GENERATORS -- SMALL QUANTITY GENERATORS FACILITY SPECIFICS

Site Name	Alumax	Produce	to Inc	ID Number	PADO49029697	Date Solo	
	1 - No Violation O	heerved	2 - Not Ar	nlicable	3 - Not Determined	4 - Non Compliance	

1	2	3	4	REQUIREMENT	PA CIT. 25 PA Code	FED CIT. 40 CFR	LINE NO.
				CONTAINERS (Subchapter I)			
K				Containers managed in compliance with 40 CFR Part 265 Subpart I and 25 PA Code Chapter 265a Subchapter I	262a.10	262.34	H025
W'				Containers of hazardous waste in good condition	265a.1	265.171	H026
W				Containers and stored waste compatible	265a.1	265.172	H027
&				Containers kept closed except during addition or removal of wastes	265a.1	265.173(a)	H028
1				Containers managed to prevent leaks	265a.1	265,173(b)	H029
Z				Container configuration and spacing insures safe management and access for inspection purposes and emergency equipment	265a.173	1. ;	H030
区				Container storage areas inspected at least weekly	265a.1	265.174	H031
		٧		Special requirements for ignitable or reactive and incompatible waste complied with	265a.1	265.176-177	H032
W				Proper containment and collection systems in place	265a.179		H033
		X		Air emission standards complied with (AA, BB, CC)	265a.1	265.178	H034
K				Containers clearly marked with accumulation date and visible for inspection	262a.10	262.34(a)(2)	H035
يع				Containers labeled "Hazardous Waste"	262a.10	262.34(a)(3)	H036
a				Containers labeled accurately identify contents	SWMA 6018.403(b) (2)		H037

Page	of	

## HAZARDOUS WASTE INSPECTION REPORT GENERATORS -- SMALL QUANTITY GENERATORS FACILITY SPECIFICS

Site Name	Alumas	Products !	Inc	ID Number	140 045029	697	Date 5/2-/	, Y
	1 - No Violatio	n Observed	1: 2 - Not	Applicable	3 - Not Determine	ed 4	- Non Compliance	

1	2	3	4	REQUIREMENT	PA CIT. 25 PA CODE	FED CIT. 40 CFR	LINE NO.
				LQG TANKS (Subchapter J)	·		
K			I	Tanks labeled "Hazardous Waste"	262a.10	262.34(a)(3)	H040
1				Written certification by registered professional engineer for proper tank (system) design and installation on file	262a.10	265.192(a)	H041
<b>X</b>				Secondary containment provided for tanks (systems) as required	265a.193	265.193	H042
A.				Tanks (systems) managed to prevent rupture, leak, corrode or fail	265a.1	265.194	H043
×				Tanks labeled to accurately identify contents	265a.194		H044
X				Required inspections completed and documented in operating log	265a.195	265.195	H045
×				Release reported to Department within 24 hours, unless exempted	265a.1	265.196	H046
		K		Special requirements for ignitable and reactive wastes followed	265a.1	265.198	H047
K	9	4		Special small quantity generator requirements	265a.1	265.201	H048
	-	-		SQG TANKS			
	口			Waste contents compatible with tank	265a.1	265.201(b)(2)	H051
	9			Uncovered tanks operated with 2 feet of freeboard or equivalent containment capacity	265a.1	265.201(b)(3)	H052
	П			If continuously fed, tank has method to stop inflow	265a.1	265.201(b)(4)	H053
				Daily tank inspection requirements complied with	265a.1	265.201(c)(1-3)	H054
		口		Weekly tank inspection requirements complied with	265a.1	265.201(c)(4,5)	H055
				All waste removed at closure	265a.1	265.201(d)	H056
9				Special requirements for ignitable or reactive waste complied with	265a.1	265.201(e)(1)	H057
				Covered tank buffer zone requirements complied with	265a.1	265.201(e)(2)	H058
9	9	9	9	Incompatible waste requirements met	265a.1	265.201(f)	H059
$\dashv$	$\dashv$	+	$\dashv$	.		· · · · · · · · · · · · · · · · · · ·	

Page	of	

EP-WM-129: Rev. 7/98

## COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION BUREAU OF LAND RECYCLING AND WASTE MANAGEMENT

#### **INSPECTION REPORT COMMENTS**

Date of inspection 08/25/2004	Identification Number PAD049029697
Company/Facility/Site Name Alumax/Alcoa	
	az. Waste inspection of the Alcoa Mill Products plant ough the facility by Steve Morinchin and Brain
Observations:	
• The site is clean and organized facility.	
The previously uncovered outside Haz. Waste a few drums present due to a recent shipment.	Storage area was enclosed and in good order with only
• Sixty- five drums of Haz. Waste were present a	and in good condition.
• The secondary containment was present in the the required documented inspections.	storage areas, and Haz Waste Tank with along with
<ul> <li>Haz waste tank was labeled as such.</li> </ul>	
PCP plan was on site and available. Source Rec	duction Strategy was dated year 2000.
<ul> <li>The facility produces about 9000 lbs of Haz. We licensed transporter with the Manifests from value</li> </ul>	Vaste per quarter and it appears it is offered to only arious states.
Manifests for the previous quarter were present	t and routed correctly.
Haz. Waste Generated in 2003	
Chromic Acid, Chromium, MEK xylenees, selenium, sodi	um, lead, mineral spirits, MEK cyclohexanone
notification of any violations observed during the inspection. Additional not herein, or other violations identified as a result of review of laboratory analyses.  This report does not constitute an order or other appealable action of imply immunity from legal action for any violation noted herein.	
Person interviewed (signature) Mailed to the site	Date
Inspector (signature) Page of	Date \$/17/64



	· / 2 ·
Inspection Date	4/28/04
Time Start	
Time Finish/	335617

## HAZARDOUS WASTE INSPECTION REPORT GENERATOR GENERATOR GENERATOR

Со	mpany name <u>Alu</u>	max froducts INC. 1.	D. Number <u>PADOY9029697</u>
Site	e Address / 450	Mankein Pika	
Co	unty <u>Le versi</u>	ter Municipality Menkeim	Two Zip 17604
		John A Pellock	
Na	me & Title of Responsi	ole Official Steve Marin chin - 1	Environmental Technician
Pe	rson Interviewed <u>ste</u>	e Marinchin, Brain Bressinger	elephone ( 7/7) 397- 964/
		nt from above) P.O. Box 3/67	
Am	nount of Hazardous Wa	ste Generated per Month:Poo	undsKgs
1.	Site Characterization	<b>:</b>	
	STORAGE: 🔀 Cor	ntainer 🗵 Tanks 🔲 Containment Bldg. 🔲 Drig	Pad Other
544(1)	PBR: Net	utralization/WWTP	Other
	GENERATOR TREAT	MENT Containers Tanks	Containment Bldg.
2.	Universal Waste:	Large Quantity Handler Small Quantity H	andler
	Universal Waste 1	ypes	
3.	Hazardous Waste Tra	ansporters:	
	Transporter Name	Clean Harbors ENV. Serv.Li	cense Number <u>MAD63132225</u> 8
		cwa chemical Serv LLC. Li	
	Transporter Name	Envirite of PS Li	cense Number PADO/0/57045
4.	Types of hazardous	waste generated and destination facility (locatio	n & type).
	Waste Code	Waste Description	Destination Facility
		RO un to sout - latel	slean Hebres of
	000/	RQ waste paint related	l ·
	D001	Ra weste solids, Flormable lig.	Baltimore, MO
		Ra weste solids, Florable lig. La weste corresive liquid	Baltinose, MO
	D001	Ra weste solids, Flormable lig.	Baltimore, MO
	D001 D002	Ra weste solids, Florable lig. La weste corresive liquid	Baltimore, MD
	000) 000) 000) 0002, 000)	Ra weste solids, Florande lig. Re weste correstue liquid Re Hoz. waste solid NO.S Re waste corr. liquid, acidic	Baltimore, MD
	000) 000)	RQ weste solids, Florande lig. RQ weste corresive liquid RQ Hoz. waste solid NO.S	Baltimore, MD

Page \_\_\_\_\_ of \_\_\_\_

### HAZARDOUS WASTE INSPECTION REPORT **GENERATORS -- SMALL QUANTITY GENERATORS**

Site Name	Alumen	Products Inc.	ID Number <u>PAP 4490 27697</u>	Date _	1/28/04

1 - No Violation Observed 2 - Not Applicable 3 - Not Determined 4 - Non Compliance

1	2	3	4	REQUIREMENT	PA CIT. 25 PA Code	FED. CIT. 40 CFR	LINE NO.
₩ W				Hazardous waste determination performed on all waste streams	262a.10	262.11	H001
				Identification Number	262a.10	262.12	H002
K	Д			Authorized transporters only	262a.10	262.12(c)	H003
				Subsequent notification requirements met	262a.12(b)		H004
K				Proper manifest used	262a.10	262.21	H005
K				Manifests filled out correctly and completely	262a.20		H006
K	Д			Manifests signed and routed properly	262a.23(a)	262.23	H007
V				Generator waste accumulated on site for 90 days or less	262a.10	262.34(a)	H008
	A			SQG waste accumulated on site for 180 days max unless 200 mile distance rule applies - 270 days	262a.10	262.34(e)(f)	H009
	A			SQG waste accumulated on-site never exceeds 6000 kg	262a.10	262.34(e)(f)	H010
	Ц			Satellite accumulation requirements complied with	262a.10	262.34(c)	H011
X				Personnel training program per 265.16 complied with	262a.10	262.34(a)(4) 262.34(d)	H012
Z.	Ц			Manifest exception and biennial reports retained for 3 years	262a.10	262.40(a)(b)	H013
k	Ц	Ц		Specified records retained for three years	262a.10	262.40(c)	H014
区	П	П		Biennial reports submitted to the Department (LQG only)	262a.41	262.41	H015
4		Ц		Exception reporting procedures followed	262a.42	262.42	H016
L.	Д	Ц		Spill reporting procedures followed	262a.10	262.34(d)	H017
E		<u>_</u>	Ц	PPC plan developed and implemented	262a.10	262.34(a)	H018
		$\mathbf{Z}$		Special requirements followed for international shipments	262a.10	262.50	H019
						262.60	
I.		<u> </u>	Ц	Source reduction strategy prepared and available (LQG only)	262a.100		H020
4	Ц	Ц	Ц	Excluded waste complies with exclusionary requirements	261a.4	261.4	H021
$\square$			_				
	$\dashv$	_					
$\sqcup$	_	_					
	_	$\downarrow$	$\perp$				

Page of	_
---------	---

# HAZARDOUS WASTE INSPECTION REPORT GENERATORS -- SMALL QUANTITY GENERATORS FACILITY SPECIFICS

Site Name <u>A</u>	lymax fooduce	to Tue ID Numbe	PADO 49029697	Date <u>7/28/09</u>
--------------------	---------------	-----------------	---------------	---------------------

1 - No Violation Observed 2 - Not Applicable

3 - Not Determined

4 - Non Compliance

1	2	3	4	REQUIREMENT	PA CIT 25 PA Code	FED CIT. 40 CFR	LINE NO.
				CONTAINERS (Subchapter I)			
K				Containers managed in compliance with 40 CFR Part 265 Subpart I and 25 PA Code Chapter 265a Subchapter I	262a.10	262.34	H025
K				Containers of hazardous waste in good condition	265a.1	265.171	H026
₽Z				Containers and stored waste compatible	265a.1	265.172	H027
&				Containers kept closed except during addition or removal of wastes	265a.1	265.173(a)	H028
<b>E</b>	Ц	Ц		Containers managed to prevent leaks	265a.1	265.173(b)	H029
×				Container configuration and spacing insures safe management and access for inspection purposes and emergency equipment	265a.173		H030
区				Container storage areas inspected at least weekly	265a.1	265.174	H031
		٧		Special requirements for ignitable or reactive and incompatible waste complied with	265a.1	265.176-177	H032
K				Proper containment and collection systems in place	265a.179		H033
		K		Air emission standards complied with (AA, BB, CC)	265a.1	265.178	H034
K				Containers clearly marked with accumulation date and visible for inspection	262a.10	262.34(a)(2)	H035
<u>~</u>	_			Containers labeled "Hazardous Waste"	262a.10	262.34(a)(3)	H036
a.				Containers labeled accurately identify contents	SWMA 6018.403(b) (2)		H037

D	
Page	ot
1 ago	OI .

# HAZARDOUS WASTE INSPECTION REPORT GENERATORS -- SMALL QUANTITY GENERATORS FACILITY SPECIFICS

Site Name Alvinas Products	ID Number	PAD 049025687	Date <u>4/28/24</u>
1 - No Violation Observed	2 - Not Applicable	3 - Not Determined	4 - Non Compliance

1	2	3	4	REQUIREMENT	PA CIT. 25 PA CODE	FED CIT. 40 CFR	LINE NO.
Ė	Ē	Ť	Ť	LQG TANKS (Subchapter J)			
K		L		Tanks labeled "Hazardous Waste"	262a.10	262.34(a)(3)	H040
8			L	Written certification by registered professional engineer for proper tank (system) design and installation on file	262a.10	265.192(a)	H041
K				Secondary containment provided for tanks (systems) as required	265a.193	265.193	H042
K				Tanks (systems) managed to prevent rupture, leak, corrode or fail	265a.1	265.194	H043
×				Tanks labeled to accurately identify contents	265a.194		H044
X				Required inspections completed and documented in operating log	265a.195	265.195	H045
R				Release reported to Department within 24 hours, unless exempted	265a.1	265.196	H046
		K		Special requirements for ignitable and reactive wastes followed	265a.1	265.198	H047
K				Special small quantity generator requirements	265a.1	265.201	H048
				SQG TANKS			
				Waste contents compatible with tank	265a.1	265.201(b)(2)	H051
				Uncovered tanks operated with 2 feet of freeboard or equivalent containment capacity	265a.1	265.201(b)(3)	H052
		$\Box$		If continuously fed, tank has method to stop inflow-	265a.1	265.201(b)(4)	H053
				Daily tank inspection requirements complied with	265a.1	265.201(c)(1-3)	H054
				Weekly tank inspection requirements complied with	265a.1	265.201(c)(4,5)	H055
	П			All waste removed at closure	265a.1	265.201(d)	H056
				Special requirements for ignitable or reactive waste complied with	265a.1	265.201(e)(1)	H057
				Covered tank buffer zone requirements complied with	265a.1	265.201(e)(2)	H058
	4	Ц		Incompatible waste requirements met	265a.1	265.201(f)	H059
	+						

_	_
Page	of

EP-WM-129: Rev. 7/98

Inspector (signature)
Page \_\_\_\_ of \_\_\_\_

## COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION BUREAU OF LAND RECYCLING AND WASTE MANAGEMENT

#### **INSPECTION REPORT COMMENTS**

Date of inspection	on <u>04/28/2004</u>	Identification Number PAD0490	29697
Company/Facilit	ty/Site Name Alumax/Alcoa		
at 1480 Manheir	late above, the Department, conducted a Ham Pike in Lancaster, PA. aefner and John Pollock were escorted through inspection.	•	•
Observations:			
• The s	site is clean and organized facility.		
	previously uncovered outside Haz. Waste so drums present due to a recent shipment.	Storage area was enclosed and in	good order with only
• Emer	rgency Response number for the Departme	ent needs updated and is 1 877 33	3 1904.(24 hour)
• Haz.	Waste drums were present and in good co	ndition. They were also labeled a	s Haz. Waste.
	secondary containment was present in the sequired documented inspections.	storage areas, and Haz Waste Tan	k with along with
• Haz	waste tank was labeled as such.		
• PCP	plan was on site and available. Source Rec	luction Strategy was dated year 2	2000.
	facility produces about 9000 lbs of Haz. W sed transporter with the Manifests from va		is offered to only
Haz. Waste Gei	nerated in 2003		
Chromic Acid, (	Chromium, MEK xylenees, selenium, sodi	um, lead, mineral spirits, MEK cy	vclohexanone
notification of any vio nerein, or other violatio This report of mply immunity from le Signature by	ction report is notice of the findings of an inspection co- plations observed during the inspection. Additional not ons identified as a result of review of laboratory analyses does not constitute an order or other appealable action of egal action for any violation noted herein.  By the person interviewed does not necessarily imply con- tereport or that a copy was left with the person.	fication of violations may be issued concer or Department records. f the Department. Nothing contained herein	rning either violations noted shall be deemed to grant or
Person interview	ved (signature) Mailed to the site	Date	

Date

ER-WM-300: Rev. 11/93 Part A

### COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL RESOURCES BUREAU OF WASTE MANAGEMENT

### HAZARDOUS WASTE INSPECTION REPORT GENERATORS - PART A

	/08/96 Ti			
Name of Inspector	Tim Grabushy			
Company, installation r	name Alumax N	1,11 Produce	<u>+5</u>	
Location	O Manheim f	he		
County Lence	5541	Municipality	Lancaster C	· 24
Identification number_	PAD 094	029 69		
Name of responsible of	ficial Dave Di	Hs		
Title	11. Engineer			
Mailing Address\	480 Markerin &	ilee Lonces	k, gr	
	ne number <u>7/7</u>	V.		
Name of person intervie	ewed <u>Ocre</u>	D.1ts		
	Enu.r			
Mailing address (if diffe	erent from above)		•	
Area code and telephor	ne number			
Current waste han	dling method:			
	treatment,	storage;	disposal disposal	☑ PBR
•	□ use,	reuse,	☐ recycle,	reclaim
•	☐ treatment,		☑ recycle,	XII recidiiii
d. ☐ Off-site	□ use,	☐ reuse,	□ recycle,	reclaim
	_	<u></u> ,	□ . 44) 4.4,	
	ous waste produced:		) /	
a	10,000	kg:/mo.	1/m0	
b		kg./yr.		
* *	us waste produced by	Hazardous Waste	Number and destinati	on facility (include
location and type)				
Waste Number	Destination I	acility	Location ar	nd Type
D039 D008	Safety Klee	n histites	rel TSD	
OCOI FOUI FOXS	Systech Envi	Corp	Demopolis 111	36732
	,	·	ALD 981 019	045
1007 1035 1007 FW3 FW5	M+M Chen + Equi	e	ALD 020 513 7	
0007	EI Dupont		NJD 002 265 7	30
DOO 1	Oldon Corp		VAN 098 443	443

Source Reduction:  $\square$  accomplished,  $\square$  proposed,  $mathbb{m}$  not proposed

ER-WM-300: Rev. 11/93

#### **COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL RESOURCES** BUREAU OF WASTE MANAGEMENT

### HAZARDOUS WASTE INSPECTION REPORT **GENERATORS - PART B**

Site Name 17 lumar Mill Prochets ID Number PAD 049 029 697 Date 108/96

#### **Hazardous Waste Inspection Report Generators - Part B**

1-No Violation Observed 2-Not-Applicable 3-Not-Determined 4-Non-Compliance

	STATUS		S	OFOLUDEMENT	CHAPTER	LINE
1	2	3	4	REQUIREMENT	CITATION	ITEM
χ				Hazardous waste determination, performed on all waste streams	262.11	H001
X				Identification number	262.12	H002
χ				Hazardous waste shipments offered only to licensed transporters .	262.12(d)	H003
χ				Authorization received from TSD facility for wastes shipped off-site within PA	262.13	H004
X				PA manifest used for intrastate shipments	262.20(b)	H005
X				TSD state manifest or PA manifest used for out-of-state shipments	262.20(c)	Н006
X				Manifests filled out properly and completely	262.20(g)	H007
X				Manifests routed properly and within time limits (7 days)	262.23(e)(f)	H008
		X		Proper U.S. DOT shipping containers or packages being used	262.30(1)	Н009
		X		Shipping containers marked and labeled according according to U.S. DOT	262.30(2)	H010
		×		Containers of 110 gal. or less permanently marked with required hazardous waste label	262.30(3)	H011
		X		Placards offered to transporter	262.33	H012
			X	Waste in containers or tanks accumulated on-site for less than 90 days	262.34(a)(1)	H013
			X	Wastes placed in containers properly marked and labeled or in tanks meeting requirements of Chapter 265, Subchapter J	262.34(a)(2)	H014
			X	Containers managed in accordance with Chapter 265, Subchapter I (any non-compliance for Subchapter I requirements is a violation of 262.34(a)(3))	262.34(a)(3)	H015
X				a). All containers of haz. waste in good condition	265.171	H016
X				b). Containers compatible with hazardous waste being stored within	265.172	H017
			X	c). Containers of hazardous waste kept closed	265.173(a)	H018
X				d). Containers of hazardous waste are managed to prevent leaks	265.173(b)	H019
			X	e). Containers of hazardous waste labelled to accurately identify contents	265.173(c)	H020
			X	f). Haz. waste accumulation areas inspected at least weekly	265.174	H021
X				g). Special requirements for ignitable, reactive and incompatible waste being met	265.176177	H022
			X	h). Proper containment and collection system(s)	265.178	H023
			X	Containers clearly marked with accumulation date and visible for inspection	262.34(a)(4)	H024
$\chi$			,	On the job or classroom personnel training program as per 265.16	262.34(a)(5)	H025

### Hazardous Waste Inspection Report Generators - Part B 2-Not-Applicable 3-Not-Determined

4-Non-Compliance

1-No Violation Observed

i	SIAIUS		•	REQUIREMENT	CHAPTER	LINE
1	2	3	4	REQUIREMENT	CITATION	ITEM
X				Records retained at designated location for 20 years	262.40(a)	H026
γ				Quarterly reports submitted to the Department	262.41(a)	H027
	X			Exception reporting procedures followed	262.42	H028
	X			Hazardous waste disposal plan, if required	262.45	H029
	Y			Spill reporting procedures followed	262.46(a)	H030
X				Preparedness, Prevention and Contingency Plan developed and implemented in accordance with Chapters 264 and 265	262.46(e)	H031
	χ			Special requirements followed for international shipments	262.50,.53, .55, .60	H032
			X	Source reduction strategy prepared and available	262.80	H033

2540-FM-LRWM0406 Rev. 10/95 Part A

## COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION BUREAU OF LAND RECYCLING AND WASTE MANAGEMENT

INSPECTION REPORT - RESIDUAL V	WASTE GENERATOR
Generator I.D. # PADC 49029697	Telephone # (7/7) 393 964/
Site Name ALUMAX	Operator Name SAME
Site Address 1480 Manhem P.he	Address
Lancistic PA 17604	L
Municipality	County Lancester
Responsible Official	Title
Person Interviewed Dave D. 1+5	Title Envil Ensineer
Inspector Jim Grabusky	Time
Inspection Date Inspection Type	nspector I.D. # # Violation
INSPECTION TYPE	
01 Routine 04 Follow Up 02 Spill Response 05 Sampling Only 03 Remedial Action 06 Ground Water	07 Complaint 08 Record Rev 09 Other
Comment	
Waste Description: Hunter Cocher Press	Sluds & Waste Code:
Treatment 🗆 Yes 🗆 No Type	
Type of Storage: Containers Tanks Piles Import	
Disposition: Destination Facility Rem tech Envir	
Location 550 Industrial Dr Lewis	
Amount Generated: 17, 3 zons Jb./mo.	y r
Waste Description: Was He O. 1 + Wa Her	Waste Code:
Treatment 🗆 Yes 🗆 No Type	
Type of Storage: Containers Tanks Piles Impor	
Disposition: Destination Facility Port In F	
Location <u>Ballimore</u> Amount Generated: 1900,000 <u>Jb./mo</u> . 5	Туре
Amount Generated: 1900, 000 lb./mo. 5	1/40
Waste Description: Wemco Grease	
Treatment	
Type of Storage: Containers Tanks Piles Impou	
Disposition: Destination Facility <u>NE Chemics</u>	T- 01.0 800 161 551
Amount Generated: 97 tons Hr./mo.	Type 0710 780 68/ 57/
Amount Generated:	

2540-FM-LRWM0406 Rev. 10/95 Part A

### COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION BUREAU OF LAND RECYCLING AND WASTE MANAGEMENT

### **INSPECTION REPORT - RESIDUAL WASTE GENERATOR**

Generator Name FLUMAX Generator I.D. # PADO4	9029697
Waste Description: P, F Sludge  Treatment □ Yes □ No Type	
Type of Storage: Containers Tanks Piles Impoundments	
Disposition: Destination Facility NE Chemical	
Location 3301 Manuel Are Cleveland OHType	
Location 3301 Montes And Clescland OH Type  Amount Generated: 4000 991 lb./mo. Y/	
Waste Description:	Waste Code:
Treatment    Yes    No Type    Petroleum Contaminiled	Ser/
Type of Storage: Containers Tanks Piles Impoundments	
Disposition: Destination Facility Miller As shalt Products	
Location 2803 Dede Rd Finks Md Type	
Amount Generated: 352 Eons /yr	
Waste Description: PLant Trash	Waste Code:
Treatment 🗆 Yes 🗆 No Type	
Type of Storage: Containers Tanks Piles Impoundments	
Disposition: Destination Facility 1050 MA Frey Form	
Location River Road Concstoss P.4 Type	
Amount Generated: 30g ころ Mr./mgo.y/	
Waste Description: Aluminum Dross	
Treatment 🗆 Yes 🗆 No Type	
Type of Storage: Containers Tanks Piles Impoundments	
Disposition: Destination Facility Scepter Endustries	
Location	
Amount Generated: 5000 600/47 lb/mo.	
A C A	
Waste Description: Refrectory Brick Waste Code:	
Treatment	
Type of Storage: Containers Tanks Piles Impoundments	
Disposition: Destination Facility LCSWNA Fire, French	
Location River Rd Conestoys PA Type	
Disposition: Destination Facility 65 MA Frey Rein  Location River Rd Cones logs PA Type  Amount Generated: 657 Cones / Heatmo.	

Generator Name 1- lumsy

#### Date \_\_\_\_\_

### **INSPECTION REPORT - RESIDUAL WASTE GENERATOR**

	olation Observed 2 = Not Applicable 3 = Not Determined	T				pliance
Chapter Citation	Requirement		Status		Line	
25 Pa Code	GENERAL PROVISIONS	1	2	3	4	Number
287.6	Designated facility: valid permit? Permit Number (PA)	X				3001
287.52(a)	Biennial report submitted by March 1 of each odd numbered year.	X				3002
287.53	Written source reduction strategy on file and in effect.	X				3003
287.53(b)	Waste reduction strategy covers all waste streams.	X				3004
287.53(c)	Reduction strategy updated every five years or when waste or manufacturing process changes.	X				3005
287.54	Waste analysis performed: copy on file.	X				3006
287.54(b, f)	Annual analysis or certification of waste submitted to Department and designated facility.	X				3007
287.55	Small quantity generator record keeping requirements.	X				3008
287.101(a)	Operation of disposal or processing facility without a permit.	X				3009
	STORAGE REQUIREMENTS					
299.111(1)	Residual waste not mixed with hazardous waste.	X				3010
299.111(2)	Waste stored as not to create a safety risk.	X				3011
299.111(3)	Residual waste not mixed with special handling waste.	K				3012
299.111(4)	Waste not blown or otherwise deposited outside storage area.	X				3013
299.112(c)	Storage area inspected; records available.			X		3014
299.113(a)	All waste stored less than one year.	χ				3015
299.114(a)	Equipment maintained in operable condition.	X				3016
299.114(c)	Equipment cleaning frequencies maintained.	Χ				3017
299.115	Vectors controlled and public nuisances prevented.	X				3018
299.116(a)(b)	Run on, runoff minimized; storage areas managed in accordance with Clean Streams Law.	χ				3019
299.116(c)	Waste stored to prevent groundwater degradation.	X				3020
299.121	Sufficient number of properly constructed storage containers.	X				3021
299.122	Storage tank design standards.	X				3022
299.112(d), 299.131(b)	No putrescible waste or liquid waste stored in piles.	X				3023
299.131	Waste storage pile area properly designed, constructed and maintained.		γ			3024
299.132	Storage pad or liner system properly designed and maintained.		X			3025
299.133	Proper design and maintenance of leachate and runoff control systems.		X			3026
299.151	Proper storage and containment of incinerator ash residue.		X			3027
299.152	Proper storage and containment of friable asbestos containing waste.		x			3028
299.153	Proper storage and containment of coal ash.		χ			3029
299.154	Proper storage and containment of PCB containing waste material.		X			3030

#### INSPECTION REPORT COMMENTS

Identification Number

Company/Facility/Site Name : Alumax Mill Products :PAD 049 029 697

Date of Inspection

:11/08/1996

On Nov. 08, 1996, Tony Rathfon and I conducted an inspection of the facility with Dave Dilts. The facility casts and rolls aluminum with several alloys. Oil and water used to cool the metal castings are separated. Castings are set outside to cool and are then rolled to various thickness. Rolls of metal are cleaned with mineral spirits and some are coated with chrome. The waste mineral spirits are pumped into a tote. The tote was not properly labeled. Since the tote is used for the collection of hazardous waste and the waste is directly piped into the tote; it may be considered part of the collection system. All hazardous waste labeling requirements are still applicable, but "collection system" may be written in place of an accumulation date.

Rolls of metal are also cleaned with a caustic solution. The caustic waste is piped to a pit, neutralized and discharged to the POTW. The Department requests to be notified when the caustic pit will be emptied to ensure it is free of cracks. Records were not available of the quantities of hazardous waste that is neutralized.

Chrome application was discontinued in the same area. There was an open, half full 55 gallon drum of chrome filter sludge located in the application is area. The container was improperly labeled as PVC pipe. An open container was noted during an inspection conducted by the Department on Jun. 08, 1993.

Rolls of metal are painted in two booths. The booths are supplied with fresh air and exhaust air is incinerated. Waste paint and solvents are reclaimed. There were three drums awaiting to be reclaimed that were not properly labeled. There was also a drum of gloves, personnel protection equipment and rags with a hazardous waste label. Writing on the Inhel was smeared and not legible. Pails containing waste solvents and paints are poured into a wash sink. The sink Grained into a cut down drum. This container was open and not labeled. None of the containers were stored with a

Person Interviewed (Signature) Ms. led	Date
Inspector (Signature) &	Date 11/18/96

Page 6 of 12

File name: ALUMAX.DOC

In the "Requirement" Section of this inspection report, each listed inspection item may provide only a brief version of its corresponding obligation as described in the body of the regulations. Please use the Chapter citations listed on this inspection report as a reference to obtain a detailed description of compliance regulirements.

This inspection report is official notification that a representative of the Department of Environmental Protection, Waste Management Program, inspected the above installation. The findings of this inspection are shown in this report. This inspection report shall serve a formal notification of any violations which were observed during the Inspection. Violations may also be discovered upon examination of the results of laboratory analyses and review of Department records. Additional notification may be forthcoming, concerning any violations indicated herein and listing any additional violations.

This report does not constitute an order or other appealable action of the Department. Nothing contained herein shall be deemed to grant or imply immunity from legal action for any violation noted herein.

Signature by the person interviewed does not necessarily imply concurrence with the findings on this report, but does acknowledge that the person was shown the report or that a copy was left with the person.

#### INSPECTION REPORT COMMENTS

Company/Facility/Site Name :Alumax Mill Products Identification Number :PAD 049 029 697

Date of Inspection

File name: ALUMAX.DOC

:11/08/1996

secondary containment and collection system. The cut down drum may not be considered part of the collection system unless waste is directly piped to it.

There was one 55 gallon drum located outside of the Jeep / forklift shop labeled as a waste oil and solvent. The drum was stored without secondary containment.

An outside hazardous waste storage area is located behind the facility. The area is a concrete pad that is fenced and locked. The pad slopes to a sump located outside of the fence. Inflow to the sump can be controlled by a valve. There was accumulated precipitation on the pad. The sump walls may be raised to prevent overflow of the sump. There were six 55 gallon drums of waste hydrochloric acid without any accumulation dates. A fax from Mr. Dilts (attached) stated that the acid was a pH of four and not a hazardous waste. There was a 55 gallon drum labeled as chrome waste filter bag with an accumulation date of May, 1996.

Hazardous and residual waste paperwork was reviewed. A written hazardous waste source reduction strategy was not available. A log was not available to show that hazardous waste accumulation areas (including tanks) are inspected.

The absence of a log noted during an inspection conducted by the Department on Sep. 19, 1989.

Person Interviewed (Signature) Mg, led	Date <u>4/19/96</u>
Inspector (Signature)	Date

Page 1/ of 12

in the "Requirement" Section of this inspection report, each listed inspection item may provide only a brief version of its corresponding obligation as described in the body of the regulations. Please use the Chapter citations listed on this inspection report as a reference to obtain a detailed description of compliance requirements.

This inspection report is official notification that a representative of the Department of Environmental Protection, Waste Management Program, Inspected the above Installation. The findings of this inspection are shown in this report. This inspection report shall serve a formal notification of any violations which were observed during the inspection. Violations may also be discovered upon examination of the results of laboratory analyses and review of Department records. Additional notification may be forthcoming, concerning any violations indicated herein and listing any additional violations.

This report does not constitute an order or other appealable action of the Department. Nothing contained herein shall be deemed to grant or imply immunity from legal action for any violation noted herein.

Signature by the person interviewed does not necessarily imply concurrence with the findings on this report, but does acknowledge that the person was shown the report or that a copy was left with the person.

#### INSPECTION REPORT COMMENTS

Company/Facility/Site Name :Alumax Mill Products Identification Number :PAD 049 029 697

Date of Inspection :11/08/1996

#### **RECOMMENDATIONS:**

- 1) Properly dispose of all hazardous waste stored on-site for longer than 90 days in accordance with Section 262.34(a)(1) of the Hazardous Waste Regulations within 30 days of the inspection on 11/08/96.
- 2) Properly close all containers of hazardous waste in accordance with Section 265.173 (a) of the Hazardous Waste Regulations within 10 days of the inspection on 11/08/96.
- 3) Properly label all containers of hazardous waste in accordance with Section 265.173 (c) of the Hazardous Waste Regulations within 10 days of the inspection on 11/08/96.
- 4) Prepare a source reduction strategy in accordance with Section 262.80 of the Hazardous Waste Regulations within 30 days of the inspection on 11/08/1996.
- 5) Ensure hazardous waste is stored in areas that are equipped with a secondary containment and collection system in accordance with Section 265.178 of the Hazardous Waste Regulations within 10 days of the inspection on 11/08/96. The height of the sump of the outside storage area may be extended to prevent overflow.
- 6) Conduct weekly inspections of hazardous waste accumulation areas on accordance with Section 265.174 of the Hazardous Waste Regulations within 10 days of the inspection on 11/08/96.
- 7) Conduct daily inspections of hazardous waste storage tanks in accordance with Section 265.195 of the Hazardous Waste Regulations within 10 days of the inspection on 11/08/96.
- 8) Seal lines and hoses entering totes and drums in a effort to prevent evaporation.
- 9) Maintain records of the quantities of hazardous waste that are neutralized in accordance with Section 265.433 of the Hazardous Waste Regulations. (Inspection of the equipment should also be conducted.)

in the "Requirement" Section of this inspection report, each listed inspection item may provide only a brief version of its corresponding obligation as described in the body of the regulations. Please use the Chapter citations listed on this inspection report as a reference to obtain a detailed description of compliance requirements.

This inspection report is official notification that a representative of the Department of Environmental Protection, Waste Management Program, inspected the above installation. The findings of this inspection are shown in this report. This inspection report shall serve a formal notification of any violations which were observed during the inspection. Violations may also be discovered upon examination of the results of laboratory analyses and review of Department records. Additional notification may be forthcoming, concerning any violations indicated herein and listing any additional violations.

This report does not constitute an order or other appealable action of the Department. Nothing contained herein shall be deemed to grant or imply immunity from legal action for any violation noted herein.

Signature by the person interviewed does not necessarily imply concurrence with the findings on this report, but does acknowledge that the person was shown the report or that a copy was left with the person.

Person Interviewed (Signature) Ms. /cd	Date 10/15/5C
Inspector (Signature)	Date 10/19/96

Page 12 of 12

### HAZARDOUS WASTE INSPECTION REPORT TSD FACILITIES - PART A

Dat	te of Inspection	6/10/97 T	ime start	Time finish	
Na	me of Inspector	RICK DALTON	,		
Cor	mpany, installation	name <u>ALUMAX E</u>	XTRYSIONS	INC FRANKLY CL	CESONA ACUMINALIA
	ation	53 Potts	Uzlle ST		
Cou	inty SCH4YLK	VIU.	Municipalit	Y ChessoNA BORG	xcH
Ide	ntification number	PAD09626252			
		official HARLY WAH			
Title	e	PLANT MAN	ACAR		
Mai	ling Address	SAA			
Are	a code and telepin	one number <u>7/7-38</u>	5-5000		
		viewed CLAY LOI			
Title	AST MANAGE	LE ENVILORMA	NTAC		
Mai	ling address (if dif	ferent from above) <u> </u>	A		
Are	a code and telepho	one number <i>SMA</i>	1		
1.	Site characteriza	tion: HAS NOT OPAK	AKD AS TS	0 STHEL 1983	
		- □ surface impoundmen		☐ physical	☐ biological
	b. 🗌 Storage -	☐ containers	☐ tanks	surface impoundments	☐ waste piles
	c. 🗌 Disposal -	☐ land treatment	□landfill	☐incineration	☐ thermal treatment
	d. 🗆 Use	reuse	☐ recycle	□reclaim	
2.	Does the facility	generate hazardous wast	e? 🗌 Yes 🗍	No	
3.	Types of hazardo	ous waste produced by Ha	zardous Waste Nu	mber:	
4.	Are hazardous w	astes transported off-site	by the facility?	☐ Yes ☐ No	

ER-WM-302; Rev. 11/93 Part 8

1-No Violation Observed

or reactive wastes

requirements

constituents

### COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL RESOURCES BUREAU OF WASTE MANAGEMENT

### HAZARDOUS WASTE INSPECTION REPORT TSD FACILITIES - PART B

ite Name ALUMAX	ID Number	PA0096262522	Date	6/19/97	
					1

2-Not-Applicable

#### Hazardous Waste Inspection Report TSD Facilities - Part B

3-Not-Determined

4-Non-Compliance

**STATUS** CHAPTER LINE REQUIREMENT **NUMBERS** MOITATD 2 3 4 H200 Part A permit application submitted 265.1(b) 265.431(a) H201 Identification number 265.11 1 Wastes accepted at facility transported by haulers licensed by DER to 265.:1(a) H202 2 transport hazardous waste H203 Waste streams not covered by permit approved by DER before 265.13(a) acceptance H204 Chemical and physical analysis repeated as required 265.13(a)(1-3) 2 H205 All waste shipments inspected and analyzed when necessary 265.13(b) 2 H206 265.13(c) 2 Waste analysis plan on-site 265.14(b)(1) H207 24 hr. surveillance at active portion H208 Artificial barrier around active portion 265.14(b)(2) H209 Proper signs posted at each entrance, minimum 4 inch lettering 265.14(c) 2 H210 265.15(b)(1) Facility inspection schedule on-site 265.15(d) H211 Maintenance schedule onsite for equipment or structures which reveal deterioration or malfunction H212 Immediate remedial action taken where a hazard is imminent or has 265.15(d) already occurred 265.16 H213 Approved on the job or classroom personnel training program implemented H214 265.16(f);(g) Records retained for each employee at facility of training, job title, and job description H215 Ignitable or reactive wastes separated from source of ignition or 265.17(a) reaction

H216

H217

H218

265.17(a)

265.17(b)

265.31

No smoking signs displayed where there are hazards from ignitable

Treatment, storage, disposal of ignitable or reactive wastes or mixing

of incompatible wastes or materials conducted according to

Facility maintained/operated to minimize possibility of fire, explosion, or discharge of hazardous waste or hazardous

### INSPECTION REPORT COMMENTS

Date of Inspection 4/0/9-1	Identification Number PAD0962625 222-
Company/Facility/Site Name ALUMAX EXTRU	STONS INC
CONNENTS FOR BOTH TSI	2 + GANGRAFAL DIFFERTS
FRESLETY FASMETIAN AL	TSD BUT HASAIT
OPALATAD AS SUNI STACE 1	
STORED IN TAKES & DISPOSED	
REUSED IN THE TREATMEN	
HAZARDONS NASTE IS FE	IM A NIMBER OF PARTS
OLENTERS THRONGH BUT THE	
IS DONT NASTE.	
POBIS TOOCH WASTE NON HAZ	" nisfosio OF IN UTAH.
FREELETY IS CLUSED TO SMA	L QUANTITY BANGLATOR
STATUS. IF THEY COULD SHOP	
BALTS THEY WOLLD PLOBABILLY	
PRISAT NAME LITARIVE	FRIM ORGSONA ALUMIAUM
TO GLUMAX EXTLUSTONS THE	AND THEY DID NITEF
EAG	
AZI: ENGO MANTFASTS AND I	SPURO DINA SPINES
ARA. NO DRUMS IN STRANGE	
7, 20. 10. 13.	
No Violations OBSERVED	7
This issues the section of the finition of a incoming	This report
formal notification of any violations observed during the inspection	
either violations noted herein, or other violations identified as a result  This report does not constitute an order or other appealable	of review of laboratory analyses or Department records.  e action of the Department. Nothing contained herein shall be
deemed to grant or imply immunity from legal action for any violation	noted herein.
Signature by the person interviewed does not necessarily acknowledge that the person was shown the report or that a copy was	imply concurrence with the findings on this report, but doe
Person interviewed (signature)	Date 6/10/87
Inspector (signature)	Date 6/10/47

ER-WM-300: Rev. 11/93 Part A

Date of Inspection \_\_\_\_\_\_

Name of Inspector RICK DACTON

### COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL RESOURCES BUREAU OF WASTE MANAGEMENT

### HAZARDOUS WASTE INSPECTION REPORT GENERATORS - PART A

\_\_\_\_\_ Time start \_\_\_\_\_ Time finish \_\_\_\_

Company, installation	name MUMAX EXT	RASTONS IN	C (FORMILLY CIE	SSNA ACUMINUM
	53 PUTTS			
County Schall	KILL	Municipalit	Y CLESSONA BON	COLLOT
Identification number	PAO 0962625	22		
	fficial HALLY WALL			
Title	PLANT MANK	sak		
Mailing Address				
Area code and telepho	ne number <u>7/7 - 3</u>	85-5000		
Name of person intervi	ewed CLAY CON	B	_	
Title ASST	MANAGER RAY	LINNENTAL	_	
Mailing address (if diffe	erent from above) <u>SAA</u>	1		
Area code and telepho	ne number <i>5AA</i>			
Current waste har	ndling method:		•	
a.   On-site	_	☐ storage,	disposal	□PBR
b. 🔯 On-site	☐ use,	🛛 reuse,	☐ recycle,	☐ reclaim
c. 🛛 Off-site	☐ treatment,	☐ storage,		
d. 🛛 Off-site	☐ use,	□reuse,	🛭 recycle,	☐ reclaim
a b		kg./yr.	ed ATTHERBON I	
<ol> <li>Types of hazardo location and type)</li> </ol>		Hazardous Wast	e Number and destinati	on facility (include
Waste Number	Destination	Facility	Location ar	nd Type
Dool, Do39, Door	SAFETY KLEEN		ALLENTOWN PA	
0475119H DOD7	SAFETY REGIN		DENTEN TX.	
SAL NTTHONEY	eswet			
4. Source Reduction:	☐ accomplished, <b>☑</b> pro	pposed, $\bigcap$ not pro	pposed	1 5 71

### HAZARDOUS WASTE INSPECTION REPORT GENERATORS - PART B

Site Name	ALUMAX	ID Number	PADO96262522	Date	6/10/97
-----------	--------	-----------	--------------	------	---------

#### Hazardous Waste Inspection Report Generators - Part B

1-No Violation Observed 2-Not-Applicable 3-Not-Determined 4-Non-Compliance

	STATUS STATUS		CHAPTER	LINE		
1	2	3	4	REQUIREMENT	CITATION	ITEM
Ī				Hazardous waste determination, performed on all waste streams	262.11	H001
1				Identification number	262.12	H002
1				Hazardous waste shipments offered only to licensed transporters	262.12(d)	H003
1				Authorization received from TSD facility for wastes shipped off-site within PA	262.13	H004
1				PA manifest used for intrastate shipments	262.20(b)	H005
/				TSD state manifest or PA manifest used for out-of-state shipments	262.20(c)	H006
1				Manifests filled out properly and completely	262.20(g)	H007
1				Manifests routed properly and within time limits (7 days)	262.23(e)(f)	H008
		3		Proper U.S. DOT shipping containers or packages being used	262.30(1)	н009
		3		Shipping containers marked and labeled according according to U.S. DOT	262.30(2)	H010
1				Containers of 110 gal. or less permanently marked with required hazardous waste label	262.30(3)	H011
		3		Placards offered to transporter	262.33	H012
1				Waste in containers or tanks accumulated on-site for less than 90 days	262.34(a)(1)	H01
1				Wastes placed in containers properly marked and labeled or in tanks meeting requirements of Chapter 265, Subchapter J	262.34(a)(2)	H014
1				Containers managed in accordance with Chapter 265, Subchapter I (any non-compliance for Subchapter I requirements is a violation of 262.34(a)(3))	262.34(a)(3)	H015
1				a). All containers of haz. waste in good condition	265.171	H016
1				b). Containers compatible with hazardous waste being stored within	265.172	H017
/				c). Containers of hazardous waste kept closed	265.173(a)	H018
1				d). Containers of hazardous waste are managed to prevent leaks	265.173(b)	H019
1				e). Containers of hazardous waste labelled to accurately identify contents	265.173(c)	H020
1				f). Haz. waste accumulation areas inspected at least weekly	265.174	H021
i				g). Special requirements for ignitable, reactive and incompatible waste being met	265.176177	H022
1				h). Proper containment and collection system(s)	265.178	H023
1				Containers clearly marked with accumulation date and visible for inspection	262.34(a)(4)	H024
1				On the job or classroom personnel training program as per 265-16	262.34(a)(5)	H025

### Hazardous Waste Inspection Report Generators - Part B

1-No Violation Observed 2-Not-Applicable 3-Not-Determined 4-Non-Compliance **STATUS CHAPTER** UNE REQUIREMENT **MOITATION** ITEM 2 3 4 Records retained at designated location for 20 years 262.40(a) H026 Quarterly reports submitted to the Department 262.41(a) H027 Exception reporting procedures followed 262.42 H028 262.45 H029 Hazardous waste disposal plan, if required Spill reporting procedures followed 262.46(a) H030 2 Preparedness, Prevention and Contingency Plan developed and H031 262.46(e) implemented in accordance with Chapters 264 and 265 Special requirements followed for international shipments 262.50,.53, H032 .55, .60 2 262.80 H033 Source reduction strategy prepared and available

> ALYMAX 6/10/97 PA0096262522

### **INSPECTION REPORT COMMENTS**

Date of Inspection 410/91	Identification Number PAD0962625222
Company/Facility/Site Name ALUMAX EXTRU.	
COMMENTS FOR BOTH YSL	
FACILITY PASMITTED AL	
OPALITAD AS SUNH STACE 1	
STORAD IN TAKES & DISPOSED	
REUSED IN THE TREATMEN.	
HAZARDONS WASTE IS FR	MANSER OF PACTS
OLENERS THROUGH BUT THE	
IS 0007 NASTE.	
PUBIS TO SEA WASTE NON HAZ	pislocal of IN UTAH.
FACILITY IS CLOSED TO SMA	L QUANTITY BANGER TOR
STATUS. IF THEY COULD SHOP	DOOT WASTE ON A RESULTED
BATS THEY WOULD PROBABALLY	
RECENT NAME CHANGE	FROM Chasson Aluminum
TO FLUMAX EXTRASTONS THE	AND THEY DID NITEF
EAB	
AZV: AWRO MANIFACTS AND IN	SPULED DEUN STOLINGE
ARIA. NO DRUBS IN STORME	
No Violation'S OBSERVED	7
This inspection report is notice of the findings of an inspection	conducted by a representative of the Department. This report
formal notification of any violations observed during the inspection either violations noted herein, or other violations identified as a result	
	e action of the Department. Nothing contained herein shall b
deemed to grant or imply immunity from legal action for any violation	
Signature by the person interviewed does not necessarily acknowledge that the person was shown the report or that a copy was	imply concurrence with the findings on this report, but doe left with the person.
	6/11/0-
Person interviewed (signature)	Date
Inspector (signature)	Date 6/10/97

### ALUMAX EXTRUSIONS - CRESSONA OPERATION HAZARDOUS WASTE TRACKING SYSTEM

DATE SHIPPED	DATE RCVD	WASTE IDN	CUANTITY	UNIT	TRANS. ION	TSDF ID#	SATE VANIES	TH DISP DATE
01/02/97	01/03/97	PCBFC	11927	KG	PAD980692008	OHD986975399	PAE6781316	01/24/97
01/02/97	01/03/97	PCBFC	13810	KG	PAD980692008	OHD986975399	PAE6781283	01/24/97
01/07/97	01/08/97	PCBFC	12300	KG	PAD980692008	OHD986975399	PAE6781390	01/30/97
01/08/97	01/08/97	D001\D039	62	G	ILD984908202	PAD980552020	PAE6412781	
01/14/97	01/14/97	D001\D039	77	G	ILD984908202	PAD980552020	PAE6361670	
01/14/97	01/16/97	D007	732	Р	ILD984908202	NJD002182897	NJA2586701	
01/20/97	01/21/97	PCBFC	11609	KĠ	PAD980692008	OHD986975399	PAE6781530	02/11/97
02/03/97	02/04/97	PCBFC	14173	KG	PAD980692008	OHD986975399	PAE6781541	03/06/97
02/06/97	02/06/97	D001\D039	113	G	ILD984908202	PAD980552020	PAE7597962	
02/10/97	02/11/97	PCBFC	18209	KG	PAD980692008	OHD986975399	PAE6781563	02/28/97
02/11/97	02/14/97	D007	367	P	ILD984908202	NJD002182897	NJA2586702	
02/13/97	02/14/97	PCBFC	16090	KG	PAD980692008	OHD986975399	PAE6781552	03/06/97
02/14/97	02/17/97	PCBFC	9600	KG	PAD980692008	OHD986975399	PAE6781655	03/20/97
02/17/97		Used Oil	5000	G	ELDREDGE	Inter. Petroleum Co		
02/20/97	03/21/97	PCBFC	11309	KĢ	PAD980692008	OHD986975399	PAE6781666	03/20/97
02/27/97	03/28/97	PCBFC	14290	KG	PAD980692008	OHD986975399	PAE6781681	
03/06/97	03/31/97	D007	403	P	ILD984908202	TXD077603371	SK048154	
03/06/97	03/06/97	D001\D039	68	G	ILD984908202	PAD980552020	PAE7456072	
03/06/97	03/06/97	D001\D039	15	G	ILD984908202	PAD980552020	PAE7456061	
03/06/97	03/07/97	PCBFC	12373	KG	PAD980692008	OHD986975399	PAE6781670	03/25/97
03/13/97	03/14/97	PCBFC	11800	KG	PAD980692008	OHD986975399	PAE6781692	
03/20/97	03/20/97	PCBFC	10245	KG	PAD980692008	OHD986975399	PAE6781806	
03/27/97	03/31/97	PCBFC	12336	KG	PAD980692008	OHD986975399	PAE6781784	
04/02/97	04/03/97	PCBFC	10545	KG	PAD980692008	OHD986975399	PAE6781854	04/30/97
04/03/97	04/03/97	D001\D039	210	G	ILD984908202	PAD980552020	PAE7463315	
04/09/97	05/02/97	D007	403	Р	ILD984908202	TXD077603371	SK048178	
04/10/97	04/11/97	PCBFC	9445	KG	PAD980692008	OHD986975399	PAE6781865	04/30/97
04/17/97	04/18/97	PCBFC	10782	KG	PAD980692008	OHD986975399	PAE6781703	
04/17/97	04/17/97	Used Oil	33520	P	ELDREDGE	IPC	T1895	
04/17/97	04/17/97	Used Oil	5000	G	ELDREDGE	Lancaster Oil	T1896	
04/23/97	04/24/97	PCBFC	10713	KG	PAD980692008	OHD986975399	PAE6781843	
04/25/97	04/25/97	D001\D039	60	G	ILD984908202	PAD980552020	PAE7523913	
04/30/97	05/01/97	PCBFC	9055	KG	PAD980692008	OHD986975399	PAE6781773	
05/08/97	05/09/97	PCBFC	14655	KG	PAD980692008	OHD986975399	PAE6782031	
05/15/97	05/18/97	PCBFC	9918	KG	PAD980692008	OHD986975399	PAE6782020	
05/22/97	05/23/97	PCBFC	13409	KG	PAD980692008	OHD986975399	PAE6782005	
05/23/97	05/23/97	D001\D039	120	G	ILD984908202	PAD980552020	PAE7555435	
05/29/97		PCBFC	9536	KG	PAD980692008	OHD986975399	PAE6782016	
06/05/97		PCBFC	10827	KG	PAD980692008	OHD986975399	PAE6782042	

ER-WM-300: Rev. 11/93

### COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL RESOURCES BUREAU OF WASTE MANAGEMENT

### HAZARDOUS WASTE INSPECTION REPORT GENERATORS - PART A

Date of Inspection 02	125 197 1	ime start 1000	Time finish	1200
	Jim Grabus			
Company, installation	name Alumay	Mill Produ	c +5	
	30 Manheim 1			
	caster		Lencaster C	( ty
	PAD 094			,
	ficial Dore			
Title	Envi	Ensineer		
	SAM	<del>-</del>		
Area code and telepho	ne number			
Name of person intervi	ewedS	ane		
Title		+		
	erent from above)			
Area code and telephor	ne number	V		
Current waste har	idling method:			
	☑ treatment,	storage,	☐ disposal	<b>⊠</b> PBR
b. 🖸 On-site	•	reuse,	☐ recycle,	
c. ∑ Off-site	_		☑ disposal	Z reciaiiii
d. ☐ Off-site	use,	reuse,	☐ recycle,	☐ reclaim
_	<del></del>			
	ous waste produced:	46		
	40,000	kg./mo.		•
b		kg./yr.		
<ol><li>Types of hazardo location and type)</li></ol>	us waste produced by	Hazardous Waste	Number and destinat	ion facility (include
Waste Number	Destination	Facility	Location a	nd Type
0039 0008 Safety Klain			150 Wastchester	
1001 FOOI FOOK	Systech Env.	Group	<del></del>	36732
DO01 D035			ALD 981 019 0	<del></del>
10007 FO03 FO05	M+1! Chem +	,	ALD 670 513	<del></del>
0007	EI Dupon T		WID 002 258	730
P001 -	Oldon Corp	o	VAD 098 443	443

4. Source Reduction:  $\square$  accomplished, X proposed,  $\square$  not proposed

ER-WM-300: Rev. 11/93

Part B

#### **COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL RESOURCES BUREAU OF WASTE MANAGEMENT**

### HAZARDOUS WASTE INSPECTION REPORT **GENERATORS - PART B**

Site Name Alumer Mill Products ID Number PAD 049 029 67 Date 02/25/97

#### **Hazardous Waste Inspection Report Generators - Part B**

4-Non-Compliance 1-No Violation Observed 2-Not-Applicable 3-Not-Determined **STATUS CHAPTER** LINE REQUIREMENT CITATION **ITEM** 2 3 4 262.11 Hazardous waste determination, performed on all waste streams H001 H002 262.12 Identification number Hazardous waste shipments offered only to licensed transporters H003 262.12(d) χ 262.13 H004 Authorization received from TSD facility for wastes shipped off-site within χ PΑ X H005 262.20(b) PA manifest used for intrastate shipments H006 262.20(c) χ TSD state manifest or PA manifest used for out-of-state shipments 262.20(g) H007 Manifests filled out properly and completely χ Manifests routed properly and within time limits (7 days) 262.23(e)(f) **H008** Proper U.S. DOT shipping containers or packages being used 262.30(1) H009 262.30(2) H010 X Shipping containers marked and labeled according according to U.S. DOT H011 Containers of 110 gal. or less permanently marked with required hazardous 262.30(3) waste label Χ H012 262.33 Placards offered to transporter H013 Waste in containers or tanks accumulated on-site for less than 90 days 262.34(a)(1) χ Wastes placed in containers properly marked and labeled or in tanks 262.34(a)(2) H014 X meeting requirements of Chapter 265, Subchapter J Containers managed in accordance with Chapter 265, Subchapter I (any non-262.34(a)(3) H015 compliance for Subchapter I requirements is a violation of 262.34(a)(3)) χ H016 a). All containers of haz. waste in good condition 265.171 b). 265.172 H017 Containers compatible with hazardous waste being stored within H018 Containers of hazardous waste kept closed 265.173(a) c). d). Containers of hazardous waste are managed to prevent leaks 265.173(b) H019 X 265.173(c) H020 e). Containers of hazardous waste labelled to accurately identify contents f). H021 265,174 Haz. waste accumulation areas inspected at least weekly X 265.176 - .177 H022 g). Special requirements for ignitable, reactive and incompatible waste X being met 265.178 H023 h). Proper containment and collection system(s) X

H024

H<sub>025</sub>

262.34(a)(4)

262.34(a)(5)

Containers clearly marked with accumulation date and visible for inspection

On the job or classroom personnel training program as per 265.16

#### Hazardous Waste Inspection Report Generators - Part B

3-Not-Determined 4-Non-Compliance 1-No Violation Observed 2-Not-Applicable **STATUS CHAPTER** LINE REQUIREMENT ITEM CITATION 2 3 4 Records retained at designated location for 20 years 262.40(a) H026 262.41(a) H027 Quarterly reports submitted to the Department H028 Exception reporting procedures followed 262.42 Hazardous waste disposal plan, if required 262.45 H029 X Spill reporting procedures followed 262.46(a) H030 Preparedness, Prevention and Contingency Plan developed and 262.46(e) H031 X implemented in accordance with Chapters 264 and 265 Special requirements followed for international shipments 262.50,.53, H032 X .55, .60 262.80 H033 Source reduction strategy prepared and available

#### INSPECTION REPORT COMMENTS

Company/Facility/Site Name : Alumax Mill Products

Identification Number

:PAD 049 029 697

Date of Inspection

:02/25/1997

On February 25, 1997, I conducted a follow up inspection of the facility with Dave Dilts. The facility casts and rolls aluminum with several alloys. Totes that contained waste mineral spirits were properly labeled. Quick disconnect hoses were installed to the totes. Waste minerals spirits are no longer stored in a hazardous waste tank prior to disposal. They are currently being filtered and reused.

Rolls of metal are painted in two booths. The booths are supplied with fresh air and exhaust air is incinerated. Waste paint and solvents are reclaimed. Pails containing waste solvents and paints are poured into a wash sink. The sink now drains directly into a labeled container. The container is equipped so the waste can be pumped out for reclamation. Waste paint and solvent in excess of satellite accumulation is stored inside in a fenced secondary containment unit.

The outside hazardous waste storage area is located behind the facility. The area is a concrete pad that is fenced and locked. The pad slopes to a underground tank located outside of the fence. Inflow to the tank can be controlled by a valve. All containers of hazardous waste were properly labeled.

Hazardous and residual waste paperwork was reviewed.

All waste management violations from inspections on 11/08/96 and 01/02/97 have been corrected.

In the "Requirement" Section of this inspection report, each listed inspection item may provide only a brief version of its corresponding obligation as described in the body of the regulations. Please use the Chapter citations listed on this inspection report as a reference to obtain a detailed description of compliance requirements.

This inspection report is official notification that a representative of the Department of Environmental Protection, Waste Management Program, inspected the above installation. The findings of this inspection are shown in this report. This inspection report shall serve a formal notification of any violations which were observed during the inspection. Violations may also be discovered upon examination of the results of laboratory analyses and review of Department records. Additional notification may be forthcoming, concerning any violations indicated herein and listing any additional violations.

This report does not constitute an order or other appealable action of the Department. Nothing contained herein shall be deemed to grant or imply immunity from legal action for any violation noted herein.

Signature by the person interviewed does not necessarily imply concurrence with the findings on this report, but does acknowledge that the person was shown the report or that a copy was left with the person.

Person Interviewed (Signature)  $M_a$ , lead Date 02/27/97Inspector(Signature) Date 02/27/97

 $Page_{of} 5$ 

File name:ALUMAX3.DOC

2500-FM-LRWM0276 Rev. 5/99



## COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION BUREAU OF LAND RECYCLING AND WASTE MANAGEMENT

Inspection Date	ghe,	ود .	6	٥
Time Start _				
Time Finish _		,		

## HAZARDOUS WASTE INSPECTION REPORT GENERATOR GENERATOR

Co	mpany name	umax Alumirum Corp	I.D. Number <u>BADAY 202969</u> 7
Site	e Address 141	Mankeim Pike	
Co	unty Lancaster	Municipality Menhain	Tag Zip 17604
Na	me of Inspector	John A Pollock	AT MALES
Na	me & Title of Responsib	le Official Brein Breistn	oge-
Pe	rson Interviewed	//	Telephone ( <u>2/ )</u>
Ma	iling Address (if differen	t from above) PO Box 7/	167
Αn	nount of Hazardous Was	te Generated per Month: <u>45,000</u>	Pounds Kgs
	Site Characterization:		
	STORAGE: Cont	tainer 🏿 Tanks 🔲 Containment Bldg.	Drip Pad Other
	PBR:	tralization/WWTP	Other
	GENERATOR TREATI	MENT ☐ Containers ☐ Tanks	☐ Containment Bldg. ☐ Drip Pad
2.	Universal Waste:	Large Quantity Handler	antity Handler
	Universal Waste T	ypes	
3.	Hazardous Waste Tra	nsporters:	·
	Transporter Name	Freehold Cartage INC.	License Number NSO 05 47 36
	Transporter Name	Heitage Tronsport	License Number NTO 05 47 26  License Number TNO 05 6 4 8 9 17
	Transporter Name	Sofety - Kleen	License Number SCR6060745 2
4.	Types of hazardous v	waste generated and destination facility	(location & type).
	Waste Code	Waste Description	Destination Facility
		PCB's	CWM chemical Service
			1500 Belmer Rd.
	= -		model City, NY 14107
	DO07, 0012	correstly ligaril	Acritoge ENV.
			7901 W. Maris street
			IND IN YEAR!
	FOOT, FOOZ DOOL	Flannoble liquid	Sotety- Kleen System
	0007		Linden NJ 07636

### HAZARDOUS WASTE INSPECTION REPORT **GENERATORS - SMALL QUANTITY GENERATORS**

Site Name Alamas Aluaroum ID Number 14004 902917 Date 7/26 1 - No Violation Observed 2 - Not Applicable 3 - Not Determined

	2			REQUIREMENT	PA CIT. 25 PA Code	FED. CIT. 40 CFR	LINE NO.
X				Hazardous waste determination performed on all waste streams	262a.10	262.11	H001
X				Identification Number	262a.10	262.12	H002
X				Authorized transporters only	262a.10	262.12(c)	H003
X				Subsequent notification requirements met	262a.12(b)		H004
٧				Proper manifest used	262a.10	262.21	H005
K				Manifests filled out correctly and completely	262a.20		H006
X				Manifests signed and routed properly	262a.23(a)	262.23	H007
3				Generator waste accumulated on site for 90 days or less	262a.10	262.34(a)	H008
	Y			SQG waste accumulated on site for 180 days max unless 200 mile distance rule applies - 270 days	262a.10	262.34(e)(f)	H009
	8			SQG waste accumulated on-site never exceeds 6000 kg	262a.10	262.34(e)(f)	H010
8				Satellite accumulation requirements complied with	262a.10	262.34(c)	H011
X				Personnel training program per 265.16 complied with	262a.10	262.34(a)(4) 262.34(d)	H012
¥				Manifest exception and biennial reports retained for 3 years	262a.10	262.40(a)(b)	H013
4				Specified records retained for three years	262a.10	262.40(c)	H014
X				Biennial reports submitted to the Department (LQG only)	262a.41	262.41	H015
¥	1			Exception reporting procedures followed	262a.42	262.42	H016
X				Spill reporting procedures followed	262a.10	262.34(d)	H017
7				PPC plan developed and implemented	262a.10	262.34(a)	H018
۲				Special requirements followed for international shipments	262a.10	262.50 262.60	H019
X			-	Source reduction strategy prepared and available (LQG only)	262a.100		H020
X				Excluded waste complies with exclusionary requirements	261a.4	261.4	H021
		_	-				

Page	of

### **HAZARDOUS WASTE INSPECTION REPORT GENERATORS - SMALL QUANTITY GENERATORS FACILITY SPECIFICS**

Alumentary ID Number PADOY 30 29697 Date

1 - No Violation Observed 2 - Not Applicable 3 - Not Determined

4 - Non Compliance

#### STATUS

1 2	3	4	REQUIREMENT	PA CIT. 25 PA Code	FED CIT. 40 CFR	LINE NO.
			CONTAINERS (Subchapter I)			
V			Containers managed in compliance with 40 CFR Part 265 Subpart I and 25 PA Code Chapter 265a Subchapter I	262a.10	262.34	H025
X		L	Containers of hazardous waste in good condition	265a.1	265.171	H026
X			Containers and stored waste compatible	265a.1	265,172	H027
7			Containers kept closed except during addition or removal of wastes	265a.1	265.173(a)	H028
*			Containers managed to prevent leaks	265a.1	265.173(b)	H029
×			Container configuration and spacing insures safe management and access for inspection purposes and emergency equipment	265a.173		H030
X			Container storage areas inspected at least weekly	265a.1	265.174	H031
8			Special requirements for ignitable or reactive and incompatible waste complied with	265a.1	265.176-177	H032
7			Proper containment and collection systems in place	265a.179		H033
	K		Air emission standards complied with (AA, BB, CC)	265a.1	265.178	H034
8			Containers clearly marked with accumulation date and visible for inspection	262a.10	262.34(a)(2)	H035
Y			Containers labeled "Hazardous Waste"	262a.10	262.34(a)(3)	H036
X			Containers labeled accurately identify contents	SWMA 6018.403(b) (2)		H037

Page \_\_\_\_\_ of \_\_\_

### **HAZARDOUS WASTE INSPECTION REPORT GENERATORS -- SMALL QUANTITY GENERATORS FACILITY SPECIFICS**

<b>/</b> ,			1 .
Site Name Aluman	// 10 Norm	ber <u> </u>	24 26
Site Name	<i>FT/UNIONAM</i> ID NUM	Der	Date //26 95/00
4 No Michalian Ob	Identification of the Applicable	a 2 Not Determined 4	Non-Samuellanea

1 2 3	. A	REQUIREMENT	PA CIT. 25 PA CODE	FED CIT. 40 CFR	LINE NO.
<u> </u>	T	LQG TANKS (Subchapter J)	T TOTA GODE	40 01 10	140.
री	1	Tanks labeled "Hazardous Waste"	262a.10	262.34(a)(3)	H040
×		Written certification by registered professional engineer for proper tank (system) design and installation on file	262a.10	265.192(a)	H041
ß		Secondary containment provided for tanks (systems) as required	265a.193	265.193	H042
8		Tanks (systems) managed to prevent rupture, leak, corrode or fail	265a.1	265.194	H043
		Tanks labeled to accurately identify contents	265a.194		H044
8		Required inspections completed and documented in operating log	265a.195	265.195	. H045
7		Release reported to Department within 24 hours, unless exempted	265a.1	265.196	H046
8		Special requirements for ignitable and reactive wastes followed	265a.1	265.198	H047
- X	+	Special small quantity generator requirements	265a.1	265.201	H048
		SQG TANKS			
		Waste contents compatible with tank	265a.1	265.201(b)(2)	H051
		Uncovered tanks operated with 2 feet of freeboard or equivalent containment capacity	265a.1	265.201(b)(3)	H052
		If continuously fed, tank has method to stop inflow	265a.1	265.201(b)(4)	H053
$\perp \perp$		Daily tank inspection requirements complied with	265a.1	265.201(c)(1-3)	H054
$\perp \! \! \perp$		Weekly tank inspection requirements complied with	265a.1	265.201(c)(4,5)	H055
	<u>.</u>	All waste removed at closure	265a.1	265.201(d)	H056
		Special requirements for ignitable or reactive waste complied with	265a.1	265.201(e)(1)	H057
		Covered tank buffer zone requirements complied with	265a.1	265.201(e)(2)	H058
++	+	Incompatible waste requirements met	265a.1	265.201(f)	H059

Page	 of	
raye	 UI	

EP-WM-129: Rev. 7/98

## 2056 284 COMMONWEALTH OF PENNSYLVANIA 2007 28 40 DEPARTMENT OF ENVIRONMENTAL PROTECTION BUREAU OF LAND RECYCLING AND WASTE MANAGEMENT

CONTROL COMMENT	3	27	1
Date of inspection 9/26,28/00		D049029697	
Company/Facility/Site Name Alumax Aluminum Corp., Lancasi	ter County	Ĉ.	
On the date above, the Department conducted a routine inspection of Manheim, Lancaster County. Steve Morichin and Brain Breisinger escorte	of the Alumax d John Polloc	Aluminum Corp k during inspect	p. in ion.
Back round:			
The company began operations in 1946 and has subsequently been a Manheim Pike in Lancaster County. The company employees about of sheeting and plate materials for the Auto, lighting fixture, cookw	t 1,000 people	that produce a	variety
In 1998 Alcoa purchased the facility and operates it as a subsidiary	of the firm.		
Observations:			
The facility was clean and well organized.			
The bulk of the Hazardous Waste produced at the plant results from	the painting	process.	
The outside Hazardous Waste and Residual Waste storage area is so containment but lacks cover. But according to the company official of the year.		•	the end
The extensive use of satellite accumulation points appears to be we these points. (documentation provide on training)	ll managed wi	th trained person	nnel at
A new still is present at the facility and is waiting installation. It pro Paint Line were it presently is.	obably will be	located adjacen	t to the
PPC plan was present at the plant and was produced for the inspect	ion.		, A
<del>-</del>			
This inspection report is notice of the findings of an inspection conducted by a represe offication of any violations observed during the inspection. Additional notification of violations may be other violations identified as a result of review of laboratory analyses or Department records.  This report does not constitute an order or other appealable action of the Department. Not apply immunity from legal action for any violation noted herein.  Signature by the person interviewed does not necessarily imply concurrence with the finding erson was shown the report or that a copy was left with the person.	entative of the Depoe issued concerning thing contained herings on this report,	g either violations not ein shall be deemed t	ted herel to grant (
erson interviewed (signature) Mailed to the site.  espector (signature)	Date .		
	Data	9/26.29/00	

Page \_\_\_\_ of \_\_\_

n

EP-WM-129: Rev. 7/98

## COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION BUREAU OF LAND RECYCLING AND WASTE MANAGEMENT

#### **INSPECTION REPORT COMMENTS**

Date of inspection 9/26,28/00 Identification Number	oer P	AD049029	9697
Company/Facility/Site Name Alumax Aluminum Corp., Lancaster Co	ounty		-
Analytical documentation on appropriate waste streams were present and department upon request during the inspection.	also pr	ovided to t	he
Hazardous Waste Manifests were properly filled out and complete.			
Containers of Hazardous Waste were in good condition, properly labeled	and da	ted.	
Hazardous Waste Tanks were labeled, inspected daily and equipped with	second	lary contair	ment.
Recommendations:			
The Department recommends the outside storage area be covered.			
·			
This inspection report is notice of the findings of an inspection conducted by a representative of notification of any violations observed during the inspection. Additional notification of violations may be issued or other violations identified as a result of review of laboratory analyses or Department records.  This report does not constitute an order or other appealable action of the Department. Nothing con imply immunity from legal action for any violation noted herein.  Signature by the person interviewed does not necessarily imply concurrence with the findings on the person was shown the report or that a copy was left with the person.	concerni	ing either violat	ions noted herein,
Person interviewed (signature) Mailed to the site.	Date		
Inspector (signature)	Date	9/26,29/	00

ER-WM-300: Rev. 11/93

Part B

## COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL RESOURCES BUREAU OF WASTE MANAGEMENT

## HAZARDOUS WASTE INSPECTION REPORT

ALUMAX MILL PRODUCTS - PART B

Site Name 01/02/97 ID Number PAD 049 029 697 Date 01/02/97

#### Hazardous Waste Inspection Report Generators - Part B

1-No Violation Observed 2-Not-Applicable 3-Not-Determined 4-Non-Compliance

STATUS
1 2 3 4 CHAPTER
CITATION

1	2	3	4	REQUIREMENT	CITATION	ITEM
X				Hazardous waste determination, performed on all waste streams	262.11	H001
Х				Identification number	262.12	H002
X				Hazardous waste shipments offered only to licensed transporters	262.12(d)	H003
X				Authorization received from TSD facility for wastes shipped off-site within PA	262.13	H004
X				PA manifest used for intrastate shipments	262.20(b)	H005
Х				TSD state manifest or PA manifest used for out-of-state shipments	262.20(c)	H006
X				Manifests filled out properly and completely	262.20(g)	H007
X				Manifests routed properly and within time limits (7 days)	262.23(e)(f)	Н008
		X		Proper U.S. DOT shipping containers or packages being used	262.30(1)	H009
		Χ		Shipping containers marked and labeled according according to U.S. DOT	262.30(2)	H010
		X		Containers of 110 gal. or less permanently marked with required hazardous waste label	262.30(3)	H011
		X		Placards offered to transporter	262.33	H012
X				Waste in containers or tanks accumulated on-site for less than 90 days	262.34(a)(1)	H013
			×	Wastes placed in containers properly marked and labeled or in tanks meeting requirements of Chapter 265, Subchapter J	262.34(a)(2)	H014
			X	Containers managed in accordance with Chapter 265, Subchapter I (any non-compliance for Subchapter I requirements is a violation of 262.34(a)(3))	262.34(a)(3)	H015
Х				a). All containers of haz. waste in good condition	265.171	H016
Х				b). Containers compatible with hazardous waste being stored within	265.172	H017
X				c). Containers of hazardous waste kept closed	265.17 <b>3</b> (a)	H018
X				d). Containers of hazardous waste are managed to prevent leaks	265.173(b)	H019
X				e). Containers of hazardous waste labelled to accurately identify contents	265.173(c)	H020
X				f). Haz. waste accumulation areas inspected at least weekly	265.174	H021
Х				g). Special requirements for ignitable, reactive and incompatible waste being met	265.176177	H022
			X	h). Proper containment and collection system(s)	265.178	H023
X				Containers clearly marked with accumulation date and visible for inspection	262.34(a)(4)	H024
xT	T			On the job or classroom personnel training program as per 265.16	262.34(a)(5)	H025

LINE

#### Hazardous Waste Inspection Report Generators - Part B

4-Non-Compliance 1-No Violation Observed 3-Not-Determined 2-Not-Applicable **STATUS** CHAPTER LINE REQUIREMENT 2 3 4 CITATION ITEM Records retained at designated location for 20 years 262.40(a) H026 262.41(a) H027 Quarterly reports submitted to the Department X 262.42 Exception reporting procedures followed H028 X Hazardous waste disposal plan, if required 262.45 H029 Spill reporting procedures followed 262.46(a) H030 Preparedness, Prevention and Contingency Plan developed and 262.46(e) H031 X implemented in accordance with Chapters 264 and 265 Special requirements followed for international shipments 262.50,.53, H032 .55, .60 Source reduction strategy prepared and available 262.80 H033

## COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION BUREAU OF WASTE MANAGEMENT

#### INSPECTION REPORT COMMENTS

Company/Facility/Site Name : Alumax Mill Products Identification Number : PAD 049 029 697

Date of Inspection

:01/02/1997

On Jan. 02, 1997, I conducted a follow up inspection of the facility with Dave Dilts. The facility casts and rolls aluminum with several alloys. Totes that contained waste mineral spirits were properly labeled. Mr. Dilts stated they were in the process of installing quick disconnect hoses to the totes.

Rolls of metal are cleaned with a caustic solution. During the inspection on 12/08/1996, it was believed that the caustic was a hazardous waste. Mr. Dilts now believes the pH of the waste has always been below 12.5 and thus not a hazardous waste. In the past, only the alkalinity of the waste was tested. Mr. Dilts agreed that Documentation of the current pH and the past alkalinity will be sent to the Department.

Rolls of metal are painted in two booths. The booths are supplied with fresh air and exhaust air is incinerated. Waste paint and solvents are reclaimed. There were four drums awaiting to be reclaimed. None of the drums were stored with secondary containment. Pails containing waste solvents and paints are poured into a wash sink. The sink now drains directly into a labeled container. The container is equipped so the waste can be pumped out for reclamation.

The outside hazardous waste storage area is located behind the facility. The area is a concrete pad that is fenced and locked. The pad slopes to a sump located outside of the fence. Inflow to the sump can be controlled by a valve. All containers of hazardous waste were properly labeled. A tank is scheduled to be installed in place of the collection sump, which currently has the potential for overflow.

In the "Requirement" Section of this inspection report, each listed inspection item may provide only a brief version of its corresponding obligation as described in the body of the regulations. Please use the Chapter citations listed on this inspection report as a reference to obtain a detailed description of compliance requirements.

This inspection report is official notification that a representative of the Department of Environmental Protection, Waste Management Program, inspected the above installation. The findings of this inspection are shown in this report. This inspection report shall serve a formal notification of any violations which were observed during the inspection. Violations may also be discovered upon examination of the results of laboratory analyses and review of Department records. Additional notification may be forthcoming, concerning any violations indicated herein and listing any additional violations.

This report does not constitute an order or other appealable action of the Department. Nothing contained herein shall be deemed to grant or imply immunity from legal action for any violation noted herein.

Signature by the person interviewed does not necessarily imply concurrence with the findings on this report, but does acknowledge that the person was shown the report or that a copy was left with the person.

Person Interviewed (Signature)  $M_{41/2}$  Date O1/O9/97 Inspector(Signature) Date O1/O9/97

## COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION BUREAU OF WASTE MANAGEMENT

#### INSPECTION REPORT COMMENTS

Company/Facility/Site Name :Alumax Mill Products Identification Number :PAD 049 029 697

Date of Inspection

:01/02/1997

Hazardous and residual waste paperwork was reviewed. A written hazardous waste source reduction strategy was not available. A log was not available to show that hazardous waste tanks are inspected on a daily basis.

#### PREVIOUS RECOMMENDATIONS NOT COMPLETED:

- Prepare a source reduction strategy in accordance with Section 262.80 of the Hazardous Waste Regulations within 30 days of the inspection on 11/08/1996.
- 2) Ensure hazardous waste is stored in areas that are equipped with a secondary containment and collection system in accordance with Section 265.178 of the Hazardous Waste Regulations within 10 days of the inspection on 11/08/96. The height of the sump of the outside storage area may be extended to prevent overflow.
- 3) Conduct daily inspections of hazardous waste storage tanks in accordance with Section 265.195 of the Hazardous Waste Regulations within 10 days of the inspection on 1/08/96.
- 4) Seal lines and hoses entering totes and drums in a effort to prevent evaporation.

In the "Requirement" Section of this inspection report, each listed inspection item may provide only a brief version of its corresponding obligation as described in the body of the regulations. Please use the Chapter citations listed on this inspection report as a reference to obtain a detailed description of compliance requirements.

This inspection report is official notification that a representative of the Department of Environmental Protection, Waste Management Program, inspected the above installation. The findings of this inspection are shown in this report. This inspection report shall serve a formal notification of any violations which were observed during the inspection. Violations may also be discovered upon examination of the results of laboratory analyses and review of Department records. Additional notification may be forthcoming, concerning any violations indicated herein and listing any additional violations.

This report does not constitute an order or other appealable action of the Department. Nothing contained herein shall be deemed to grant or imply immunity from legal action for any violation noted herein.

Signature by the person interviewed does not necessarily imply concurrence with the findings on this report, but does acknowledge that the person was shown the report or that a copy was left with the person.

Person Interviewed (Signature) No. /c Date 01/09/97
Inspector(Signature) Date 01/09/97

Page 8 of 8

# **EVALUATION - VIOLATION - ENFORCEMENT FORM**

Handler ID Number Handler Type	NAE
	19
Handler Name Contact Name Date Submitted	
Street Street ALUMAY MILL PRODUCTS MR DAVE DILTS 0:6 2:5 9:3	
P.U. BOX 3167 LANCASTI PA	
EVALUATION Add Change Delete	
Date Number Agency Type Reason Branch Person	
0:60:819:3 5 CEI P.4.C.4.Z	
AREAS OF EVALUATION ( E - Evaluated NE - Not Evaluated NA - Not Applicable )	
GER GPT E GBF TWD DGS E TO DPB NE DWP NE	
GGR E GRR C TGR DCH NE DGW NE DMC NE DPP NE DBF NE	
GLB E GSC TMR DCL E DIN E DMR WE DSI NE CAS NE	
GMR E GSQ E TOR DCP NE DORNE DTR NE FEA NE	
GOR E GEX WE TRR FR WE OLF WE DOT DIT WE CSS WE	
Comments LOG INSPENSION FULL FROM TSF STATUS - SEE ATTACHED DE	C4H6N
OUTSTANDING VIOLATIONS COV. ED B. TO EVALUATION	
Agency Number Area te Dey Aned Agency Number Area Date Determined	
	à:
VIOLATION A Change Delete Link to Above Evaluation? (Y/N)	
Agency Numbe Area Class Regulation Type Regulation Citation	
	en e
Returned to Compliance	***
Determined Priority Branch Person Scheduled Actual	
	-
Completes	
VIOLATION Add Change Delete Link to Above Evaluation? (Y/N)	
Agency Number Area Class Regulation Type Regulation Citation	
Returned to Compliance	
Date Determined Priority Branch Person Scheduled Actual	
Comments	

Required Required if pertinent Required only for previously reported data

### Pennsylvania Department of Environmental Resources Bureau of Waste Menagement

#### Hazardous Waste Inspection Report Generators — Part A

Date of inspection 11 June 1993 Time start 10:10 Am	Time finish 12:10 PM								
Name of inspector Cher Zeller, Ravdy Wein, Tony Rothfor									
Company, installation name ALUMAY Full Products									
Location Box 3167 Lancaster PA 17604 (Mon	heim Dife)								
County LANCASTON Municipality _	LANCASTER CITY								
Identification number PAD 049 029697	/								
Name of responsible official MR. DAVID DILTS									
Title ENVIRONMENTAL ENCINEER									
Mailing address BOX 3167, LANCASTOR PA 17604									
Area code and telephone number (7/7) 393 - 9641									
Name of person interviewed MR. DAVID DICTS									
Title ENVIRUNMENTAL ENGINEER									
Mailing address (if different from above)									
Area code and telephone number									
1 Current words handling models.									
1. Current waste handling method:	" DDD								
,	disposal PBR								
	recycle,								
,	disposal								
d. 🗆 Off-site 🗆 use, 🗆 reuse, 🗆	recycle, reclaim								
2. Amount of hazardous waste produced:	•								
a. <u>12,000</u> kg./mo.									
b kg./yr.									
3. Types of hazardous waste produced by Hazardous Waste Number and	destination facility (include location and type).								
Waste Number Destination Facility	Location and Type								
DOOI FOLVENT NE Chemical TSD	3301 Monroe Ave (TSD)								
2001/F003/F005 NE Chemical TSD	Chreland, Olio 44113								
2001/F003/F005 NE Chemical TSD	<i>II II</i>								
Fairy + Ruge									
019 Chrome Aludae AMAX Metals Recovery	LA Hughway 3137 Braithwrite 470								
	1								
2001 Hiveral Spirits Center Inc / NE Chemical	3301 Monroe Ave								
- ' /	Clircland, Otrio 44113								

Recycled Paper

## Paursylvania Department of Environmental Resources Bureau of Waste Management

### Hazardous Waste Inspection Report Generators — Part B

Aluxaf Will Products FAD 049029697 14 June 93

	· 1-N	o Viol	ation Observed 2—Not Applicable 3—Not Determined 4—Non-Compl	
<del></del>	tus		REQUIREMENT NEW?	Chapter Citation
- 2	3	4	CITATION .	75.262
			Hazardous waste determination, copies available 262.11	(b) .
-			Identification number 262.12 (a)	(c)(1)
			Hazardous waste shipments offered only to licensed transporters  262.72 (4)	(c)(4)
			Authorization received from TSD facility for wastes shipped off-site 262.13	(d)
			PA manifest used for intrastate shipments 262.20 (b)	.(e)(2)
			Disposer state manifest or EPA format manifest used for out-of-state shipments 262.20(c)	(e)(3)
eggine.		·	Manifests filled out properly and completely	(e)(7)
			Manifests routed properly and within time limits (7 days) $262.23(e) - (f)$	(e)(14) or (1
			Proper U.S. DOT shipping containers or packages 262.30 (1)	(f)(1)(i)
			Shipping containers marked and labeled according to U.S. DOT 262.30(2)	(f)(1)(ii)
			Containers of 110 gal. or less marked with required PA label 262.30(3)	(f)(1)(iii)
1	-X		Placards offered to transporter 262. 33	(f)(2)
		ર્જ : સ્વર્ષ	Wastes accumulated on-site for less than 90 days 262.34 (a)(1)	(g)(1)(i)
ļ "			Wastes stored in proper containers and properly marked and labeled 262.34(4)(2)	(g)(1)(ii)
	بغز	·	Containers managed in accordance with 75.265(q)(1)—(3)(17).	(g)(1)(iii)
<u>'</u>			Containers clearly marked with accumulation date and visible for inspection 262.34 (a) (4)	(g)(1)(iv)
٧			Records retained at designated location for 20 years 262.46	(h)
			Quarterly reports submitted to the Department 262.41	(i) ·
			Exception reporting procedures followed 262.42	(j) · - 4
			Hazardous waste disposal plan, if required 262.45	(I) ÷ 7°
<u> </u>		•	Spill reporting procedures followed 262.46 (4)	(m)(1)
			Preparedness, Prevention and Contingency Plan and implemented 262.46 (e)	(m)(5)
K			Special requirements followed for international shipments 262.50 262.53	(a) .
			On the job or classroom personnel training program [75.265(f)] 262.34(a)(5)	(g)(1)(B)
			Orum accumulation area inspected weekly as per 75.265(q)(5) 262.34(a)(3)	(g)(1)(iii)
			The second of th	
E TO SE S				ر در د
	· .			ت د دست می د

#### Commonwealth of Pennsylvania Department of Environmental Resources Bureau of Waste Management

### **Inspection Report Comments**

	Identification Number PAD 049029697
Company/Facility/Site Name ALUMAY MILL PRODE	VETS LANCASISM PA.
Cher Feller Randy Wein and Ton	ry Rathfor (PA Don) arrived at the plant
at 10:00 AM and mes Mr. Dave &	litte (environmental engineer). All parties
	the hazardour worte storage was. All the
	e labeled and stored properly with the
following deeption: I drew	of F003/F005/D001 (Kylene tollene) and I drum of
	revent in the compound longer than the 90 day
allowed. There drung are schedules	I for disposed as the earliest opportunity.
(noted:	loss the following waite stream were
2001 - Solvent Foo:	3/1005 Pant + Rage, Forg Chrome Aludge
DO01 - Mineral Spirit	
and disposal plans sevealed no	- dicrepance. Land ban sestriction docum
were evident and in use.	
TSD status was discussed and	documentation is attached to serve this
Pacility from previous EPA lis	ting as To.
This presention was consleted	1 ST 12:10 PM.
its corresponding obligation as described in the body of tion report as a reference to obtain a detailed descrip This inspection report is official notification that a of Waste Management, inspected the above installatio tion report shall serve a formal notification of any viola be discovered upon examination of the results of labor tion may be forthcoming, concerning any violations in This report does not constitute an order or other a deemed to grant or imply immunity from legal action	representative of the Department of Environmental Resources, Bureau in. The findings of this inspection are shown in this report. This inspections which were observed during the inspection. Violations may also ratory analyses and review of Department records. Additional notificandicated herein and listing any additional violations. Appealable action of the Department. Nothing contained herein shall be for any violation noted herein.
Person Interviewed (signature)	Date
Inspector (signature) Cherry A. Tw	- Date 14 June 93
	/ Fana of



Box 3167 Lancaster, Pennsylvania 17604 (717) 393-9641 Telex: 84-8436

November 17, 1989

DER
WASTE MANAGEMENT
NOV 2 0 1989
HARRISBURG REGION

Mr. Thomas J. Hanlon Pennsylvania D.E.R. Bureau of Waste Management One Ararat Boulevard Harrisburg, PA 17110

Subject: Final Closure: Alumax Mill Products, Inc.

Hazardous Waste Tank Storage Area

PAD049029697

Manheim Township, Lancaster County

Dear Mr. Hanlon:

Please find enclosed two (2) items per subject:

- 1.) "Owner or Operator Certification of Closure"
- 2.) "Professional Engineer Certification of Closure"

Should you have any further questions or requests concerning the above, please contact me.

Sincerely,

Alumax Mill Products, Inc.

Stephen C. Kirchner' Environmental Supervisor

SCK:jer enclosures (2) cc: G. Lanza

R. Martin

#### OWNER OR OPERATOR CERTIFICATION OF CLOSURE

. The undersigned, ALUMAX MILL PROD	DUCTS, INC., a (1) Corporation,
(Name of Ow	vner or Operator)
incorporated under the laws in the State of DEI Pennsylvania, or (2)	LAWARE and licensed to do business in
(Partnership, Individu	ual, Municipality or Other Entity)
with its principal place of business at 1480 MANHE	
formerly owned or operated a hazardous waste	STORAGE FACILITY
(hereinafter "Facility") known as _ALUMAX MILL	
located at 1480 MANHEIM PIKE LANG	
	ocation)
in <u>LANCASTER</u> County, Pennsylvania, has active operation of the facility and has fully important of the facility as set forth in the Closure Department of Environmental Resources for sai	e Plan approved by the Pennsylvania
NOW, THEREFORE, I (we)ALU	JMAX MILL PRODUCTS, INC. (Name of Owner/Operator)
by the Closure Plan and the rules and regulation Chapter 75 have been fully implemented, and the	elating to the closure of the facility required as of the Department codified at 25 Pa. Code nat to the best of my (our) knowledge, no
violations continue to exist that may have arise	n prior to closure.
GUY C. LANZA Buy Chanto	
Walkingtone	
VICE-PRESIDENT & GENERAL MANAGER (Title)	
1480 MANHIEM PIKE LANCASTER, PA 17604 (Address)	
Taken, sworn and subscribed before me, this  17.4 day of November A.D. 1989	
Janue Cillen Hoalrs	
The Cities 10 good	

Notarial Seal Janice Eileen Rogers, Notary Public Manheim Twp., Lancaster County My Commission Expires Oct. 23, 1993

Member, Pennsylvania Association of Notaries

#### PROFESSIONAL ENGINEER CERTIFICATION OF CLOSURE

I, Dr. Harry H. West, a Professional Engineer registered pursuant to the Professional Engineers Registration Law, 63 P.S. #148 et seq., hereby certify that I have received the Closure Plan for the Hazardous Waste Storage Tank at Alumax Aluminium Corporation ("facility"), located at 1480 Mannheim Pike, Lancaster, Pennsylvania 17604 that I am familiar with the rules and regulations of the Pennsylvania Department of Environmental Resources pertaining to closure of such facility, and that I personally have made visual inspection(s) of the aforementioned facility, and that the closure of the aforementioned facility has been performed in full and complete accordance with the facility's closure plan approved in writing by the Department of Environmental Resources on June 30, 1988, and the rules and regulations of the Department codified at 25 Pa. Code Chapter 75.

D. H. Huly

November 10, 1989

Pennsylvania Professional Engineering Number..PE-035611-E

Consulting Chemical Engineer Environmental Management Consultants 175 Springfield Road Landisville, PA 17538 717-898-7721 BUREAU OF WASTE MANAGEMENT
Harrisburg Regional Office
One Ararat Boulevard
Harrisburg, Pennsylvania 17110
(717) 657-4588
January 8, 1990

Mr. Stephen C. Kirchner Environmental Supervisor Alumax Aluminum Corporation 1480 Manheim Pike Box 3167 Lancaster, PA 17604

Re: Alumax Aluminum Corporation
Closure Plan
PAD 049029697
Manheim Township, Lancaster County

Dear Mr. Kirchner:

On September 18, 1989, Mr. Glenn Mitzel, Mr. Donald Hentz, and I inspected the former hazardous waste tank and collection area at the above referenced facility. The purpose of this inspection was to determine if closure had taken place as described in the Department approved Closure Plan. The Closure Plan was approved by the Department on June 30, 1988.

Based on that inspection and the Owner/Operator and Professional Engineer Closure Certification submissions, we hereby certify that the facility has been closed in accordance with the approved Closure Plan.

If you have any questions, please contact this office.

Sincerely,

Thomas J. Hanlon Hazardous Waste Coordinator Harrisburg Regional Office

#### TJH:fdb

bcc: Rebecca Hinderliter, Central Office
Glenn Mitzel
File

ER-WM-119: 9/88  Commonwealth of Pennsy Department of Environmental Bureau of Waste Manage	Resources
Inspection Report/D	ata Entry
Site I.D. # PADOK190219161971 Tele	phone #393-9641
<b>A</b> /	rator Name
	ress
Committee of the commit	·
Municipality Cou	inty LANCAS to
Responsible Official Steve Kirchnen Title	Environmental Sepervisor
Person Interviewed Title	
Inspector Glenn Mitzel, Tom Hanlow Time	e
	acility
- 0.C - 0 BCC	Type Inspector I.D. # # Violation
0911181819 613111818131 611	2337
Comment TSD STATUS	
Sample # Low Sample # High	
Monitoring Points Sampled	
INSPECTION TYPE	FACILITY TYPE
Municipal	Residual Hazardous
01 Routine 10 Survey 01 Municipal Waste Land	Ifill 06 Landfill 01 Disposal
02 Spill Response 11 Part B 02 Construction/Demolities	
03 Remedial Action 12 Complaint Landfill	08 Processing 03 Storage
04 Follow Up 13 Withdrawn 03 Processing 05 Crit Stage 14 Closure 04 Incinerator	09 Incinerator 04 Transporter
	10 Surface Application 05 Permit by Rule 11 Surface Impoundment 06 Generator
06 Sample Only 15 Post Closure 05 Surface Application 07 Permitting 16 Form 4	12 Surface Injection Well 07 SQG
08 Superfund 17 Form 4 w/sample	O8 RRR
09 Ground Water 50 Record Rev	09 Other
99 Other	50 Superfund

AWASTERFERD

#### PRINCE DEPARTMENT OF ENVIRONMENTAL RECOURCES

### Hazardous Waste Inspection Report Generators — Part B

		_ !!	re Ale	lation Observed 2—Net Applicable 3—Net Determined 4—Nen-Co	mpilence
Status 1 2 3 4				REQUIREMENT	Chapter Citation
					75.262
1				Hazardous waste determination, copies available	(b)
l	·			Identification number	(c)(1)
ı				Hazardous waste shipments offered only to licensed transporters	(c)(4)
				Authorization received from TSD facility for wastes shipped off-site	(d)
ſ				PA manifest used for intrastate shipments	(e)(2)
				Disposer state manifest or EPA format manifest used for out-of-state shipments	(e)(3)
ı				Manifests filled out properly and completely	(e)(7)
		3		Manifests routed properly and within time limits (7 days)	(e)(14) or (1
i				Proper U.S. DOT shipping containers or packages	(f)(1)(i)
				Shipping containers marked and labeled according to U.S. DOT	(f)(1)(ii)
•				Containers of 110 gal. or less marked with required PA label	(f)(1)(iii)
		3		Placards offered to transporter	(f)(2)
				Wastes accumulated on-site for less than 90 days	(g)(1)(i)
				Wastes stored in proper containers and properly marked and labeled	(g)(1)(ii)
			4	Containers managed in accordance with 75.265(q)(1)—(9)	(g)(1)(iii)
	•			Containers clearly marked with accumulation date and visible for inspection	(g)(1)(iv)
				Records retained at designated location for 20 years	(h)
				Quarterly reports submitted to the Department	(i)
٦	2_			Exception reporting procedures followed	(i)
	2			Hazardous waste disposal plan, if required	(1)
				Spill reporting procedures followed	(m)(1)
				Preparedness, Prevention and Contingency Plan and implemented being return	(m)(5)
	2			Special requirements followed for international shipments	(0)
	•	3		On the job or classroom personnel training program [75.265(f)] head decumentation	(g)(1)(6)
			4	Drum accumulation area inspected weekly as per 75.265(q)(5) Craate a log.	(g)(1)(iii)
+					
$\perp$					

#### Pennsylvania Department of Environmental Resources Bureau of Waste Management

### Hazardous Waste Inspection Report Comments — Part C

Date of Inspection 9/18/89 Identification Number PADO 49029697  Company, Installation Name ALMAX ALMINUM CORP.
Company, Installation Name ALMAX ALMINUM CORP.
County <u>LANCASTER</u> Municipality <u>Manheim Tashp.</u>
Glenn Mitzel, Don Hentz Any Tom Handon from the
Department met with Steve C. Kirchner (Environ.
Sipervisor on - site for an ingrection.
Sipervisor og-site for on inspection.  Aluman greates \$\textstyle 001 - 0ff-5pec. paint  DOGG - Baghouse Dust (Cd)
DOGG - Bashouse Dust (Cd)
TRANSPORTERS ~30 Tons /mo.
2001 - ECOLUTECH (STOUT) FOIG - Filter Studge from
Worlewsten IntCRHOCK
2200016/yr.
FOOS - STILL BOTTOM, MEK
TRANSPORTES 200 TOUS.  201 - ECOLOTECH (STOUT) FOIG - Filter profession Landewater Int CRHOCK  DOOG Westo Conversion - 22 000 lb/yr.  FOOS - STUL Bottom, MEK  5019 - Envinte worter 3 chum/90 days.
Foot - Eldridge, Inc
Presently, Alumax is listed under TSD STATUS.
MEK Waste from painting operations was stored
in a 10,000g ABOUF GROUND STORAGE TANK AND SHIPPED
2 every 7mb. (Report 3/9/87). It Is NOW empty
a closure was submitted Ann Approupo, TESTING HAS BEEN
PONE + Abuman is Awaiting Certification of closure as A TSD.
THINNER WARTE IS NOW DISTILLED + RECYCLED.
This inspection report is official notification that a representative of the Department of Environmental Resources, Bureau of Waste Management, inspected the above installation. The findings of this inspection are shown in this report. Any violations which were uncovered during the inspection
are indicated. Violations may also be discovered upon examination of the results of laboratory analyses and review of Department records. Notification will be forthcoming, confirming any violations indicated herein and listing any additional violations.
Person Interviewed (signature) Service
nspector (signature) Henry J. mtyl Date 9/18/89
V

### Pennsylvania Department of Environmental Resources Bureou of Waste Management

### Hazardous Waste Inspection Report Comments — Part C

Date of Inspection 9/18/89	Identification Number PADO49 0 29 697
Company, Installation Name Alumin	um Corp.
County - LANCAS TEX	Municipality Manheim Tuckp.
oil westers The major	Solid noste at this facility.
Alemax somerates 904	386 galles of oil waste for.
The oil is burned a?	\$86 galles of oil wante fyr.  Bethlehen Stell-MD
Pori honeporta	+ processed waster.
IN the maintenan	ce one I drum of
SAF. T-SOL Solvent w	ate had on open burg.  dosed who not making
ARES Downs should be	dosed who not making
additions.	
- Them Storage Are	a need to be inspected
weekle as rea	oper of new PPC. plan
- Dest will reed a c	very of new PRC. slan
when sompleted.	. 0
Resources, Bureau of Waste Management, inspin inspection are shown in this report. Any violation are indicated. Violations may also be discovered.	representative of the Department of Environmental ected the above installation. The findings of this ons which were uncovered during the inspection of upon examination of the results of laboratory fication will be forthcoming, confirming any violations.
rerson Interviewed (signature)  Sector (signature)  Sector (signature)	Date 9-18-89  Date 9/18/89
isharini (siAilaima)	Date

### UNITED STATES ENVIRONMENTAL PROTECTION AGENCY **REGION III**

841 Chestnut Building Philadelphia, Pennsylvania 19107

SUBJECT: RCRA Inspection ALUMAK ALUMINUM CORP.

DATE: 4/15/87

PAD 04 902 9697

FROM:

Joseph S. Arena -18A

Environmental Scientist (3HW11)

TO:

File

Thru:

Peter W. Schaul, Chaef

RCRA Enforcement Section (3HW11)

BASED UPON A REVIEW OF THE RCRA INSPECTION REPORT FOR THE FACILITY REFERENCED ABOVE, I HAVE DETERMINED THAT NO FURTHER ACTION IS REQUIRED AT THIS TIME.

## MMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL RESOURCES BUREAU OF SOLID WASTE MANAGEMENT

### **INSPECTION REPORT**

Site ID # PAD 049 029 697  Site Name: ALUMAN ACUMING Address Bex 3167  City LANCASTER  Municipality MANNEIM  Responsible Official Person Interviewed STEPHEN C.  Inspector Doug Zimmer L	KIRCHNER	State <u>P4.</u> County	LANC.	Zip Code <u>1760</u> タ				
Inspection Type  01 Routine 04 Follow Up 05 Crit Stage 06 Sample Only 07 Permitting 08 Superfund 09 Ground Water 10 Survey  11 Part B 12 Complaint 13 Withdrawn 14 Closure 15 Post Closur 50 Record Rev 99 Other		ne Ha v Up Re le Mu y laint d Rev	zardous 🖳 sidual 🗆 unicipal 🗆	Treatment  Storage  Disposal  Generator  Processing  Surface App  Transporter				
Site ID # PADO1902969	7	,	On-Site Start Ti On-Site End Tim On-Site Total Ti	e 2:00				
Due Date Inspection Date	Туре	Inspector ID #	# Violation	Enforcement				
030987 030987	511	2323	01					
Comment NO 4CCUMULATION DATES								
Sample # Low Sample # High								
Monitoring Points Sampled								

ER-WM-116: Rev. 1/86

## C MONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL RESOURCES BUREAU OF WASTE MANAGEMENT

FACILITY NAME

## LUMIS VIOLATION ENTRY

AMOUNT

ID#	14 20 49 029	697	Violation Date	030987	
Violation #	Source Class	Comment (24 Ch	NATES		For Source Use Inspection Type Codes on Inspection Cover Form
			• • • • • • • • • • • • • • • • • • •		Additional Violation Codes  Ol6 Container Labeling Ol7 Container Condition Ol8 PPC Plan Ol9 Exception
					Reporting 020 Employee Training 021 Hz Waste Determination 022 Litter Contract 023 Operational Reports 024 Gas & Odors
					Date Due  Date Complied  Enforcement
Violation Code 001 002 003 004 005 006	Violation Description Off Permit Area Above Contours GW Monitoring Waste Type Timely Reclamation Leachate Control	Violation Code 007 008 009 010 011 012	Violation Description Sig Deviation - Design Financial Report Quarterly/Annual Report Manifest Cover UN/Improp Lic Transp	Code D 013 C 014 O 015 E 099 O	Action Type  iolation escription losure/Post Closure perating without Permit or Interim Status &S Control ther

241...

				1- NOIL-COMPUANCE, Z-COMPUANCE, 3-NOT APPLICABLE, 4-NOT DETERMINED	
ON			F		CHAPTE
ST	ATU	3	+	REQUIREMENT	75.262
	- - -/-		1	Identification number	(c) (1)
+		1	+	Hazardous waste shipments offered only to licensed transporters	(ċ) (4)
1		1	$\dagger$	Authorization received from TSD facility for wastes shipped off-site	(d)
+	7	7	+	PA manifest used for intrastate shipments $(e)(a)$	<del>(e) (1)</del>
	1	1	1	Disposer state manifest or EFA format manifest used (e)(3)	<del>(e) (1)</del>
	7	7	1	Manifests filled out properly and completely $(e)(7)$	<del>(a) (1</del>
1	1			Manifests routed properly and within time limits (24 hours) (2) (14) cr (15)	<del>(a) (2)</del>
T	~ I	1		Proper U.S. DOT shipping containers or packages	(£) (1
			1	Shipping containers marked and labeled according to U.S. DOT	(f)(1)
	1			Containers of 100 gal. or less marked with required PA label	(f)(1)
			1	Placards offered to transporter	(£) (2
				Wastes accumulated on-site for less than 90 days	(g) (1
1	/			Wastes stored in proper containers and properly marked and labeled	(g) (1
	1		Ì	Containers managed in accordance with 75.265( $\Re$ $(q)(1)-(q)$	(g) (1
				Containers clearly marked with accumulation date and visible for inspection	(g) (1
	1			Records retained at designated location for 20 years.	(h)
	V			Quarterly reports submitted to the Department	(i)
				Exception reporting procedures followed	(j)
		,		Hazardous waste disposal plan, if required	(1)
				Spill reporting procedures followed	(m) (1
	V			Preparedness, Prevention and Contingency Plan approved and implemented	(m) (5
		~		Special requirements followed for international shipments	(0)
	<u>ر</u>			On the jeb or classroom personnel training program [15.205(F)]	(3/1)
/	_			Drum accumulation area inspected & inspection logged daily as per 15265(1)	1(9)(1)
	_	_	_	. いたでメレy	
-	_	_	_	Victorial Commence	
				·	

## - - HAZARMOUS WASTE INSPECTION REPORT Part C - Comments

Date of Inspection 03-09-87	Identification Number 745 049029697
Company, Installation Name ALUMAX Box	: 3167 LANC. PA. 17604
County LANC. Municip	
•	
ALU MAX MANUZACTUZI	E ALUMINUM INGOTS AND
	OUS PRODUCTS (CANS, PLATES ETC.)
THE BASIC OPERATION CONSISTS OF	
CAST HOUSE -> HOT MILL -> COLD H	TILL -> MILL EINISHING -> PAINTLIM
FROM THESE OPERATIONS THE	FOLLOWING HAZARDOUS
WASTE IS GENERATED DOO	1, DOOD, FOIG FOOS FOOS
ON FEB 20th 1987 A4	LETTER WAS SENT TO
BOR BENVIN PA. D.E.Z FRO	
ALUMAX. THE LETTER STA	THAT ALUMAX PLANNED
TO COSE WITHDRAW ITS	PART B APPLICATION AND
BEGIN TO CLOSE THE A	HBOVE CROUND M.E.K.
STORACE TANK (10,000 C-AL)	CUZZENILY THE TANK
	MTHS. IN THE FUTURE
THEY PLAN TO INSTALL	A SOLVENT DISTILL ATION
UNIT TO MINE PILE	- PEPLACE SOLVENT STORAGE
This inspection report is official notification th	nat a representative of the Department of
Environmental Resources, Bureau of Solid Waste Mar The findings of this inspection are shown in this	nagement, inspected the above installation.
during the inspection are indicated. Violations $\pi$	may also be discovered upon examination of
the results of laboratory analyses and review of I forthcoming, confirming any violations indicated h	Department records. Notification will be
	. 7
Person Interviewed (signature) (signature) Courtle E. Jimmen	Date 3/9/87

#### UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Region III — 6th & Walnut Sts. Philadelphia, Pa. 19106

SUBJECT: RCRA Inspection-

Howmet Aluminum Corp PAD049029697

DATE: April 27, 1983

William L. Walsh, Environmental Protection Aid with FROM Superfund/RCRA Compliance Section (3AW23)

TO: File

Walter F. Lee, Chief Thru:Superfund/RCRA Compliance Section (3AW23)

BASED UPON A REVIEW OF THE RCRA INSPECTION REPORT FOR THE FACILITY REFERENCED ABOVE, I HAVE DETERMINED THAT NO FURTHER ACTION IS REQUIRED AT THIS TIME.

المراجع	PHONE CALL DISCUSSION	FIELD TRIP CONFERENCE	
RECORD OF		FIELD TRIP CONFERENCE	
COMMUNICATION	OTHER (SPECIFY)	abouted about	
TO: /		m checked above)	-{
DONALD KILLIAN	FROM: Bill Walsh	4/33/92	
PA DER (717) 787-9697	KCRA COMPLIANCE	TIME 8 15 AM	1
SUBJECT			1
follow up on 7/13/91 ing	cection of Hound U	Myminum logs. (PAD 04	902
Total Ma	Villian Back him is	Howard Aluminum	9697
1 1 1 that a du	and at A herica her	inquictio. He stated	
losp. had corrected the proble	me craw wiring nor	ingersal 1-44	
the state of	culity during the fa	My 1981 and out	
The he had reinspicted the for	chines with all ne	cernary Myalaliend.	
While was now in conf	solure cons	// //	
#			İ.
			1
			1
CONCLUSIONS, ACTION TAKEN OR REQUIRED			i na
		•	
			·
	·		
INFORMATION COPIES			1
то:		1	1



# TSD Facilities - Part A

Date of inspection 7-13-31 Time start /:301 Time firsh 2:5091
Name of inspector Downie L. KILLIAN PROMES L. DALLA PIRTA
Company, installation name However Products Du
Location 1480 MANNEW PINE LANGUER
County Learnesser Municipality Ministry Tor
Identification number Privacy Correct Correction Control Correction Control Correction Control Correction Control Correction Correction Control Correction
Name of responsible official N.C. (Suy LANZ)
Title FLANT PHUAGEN
ailing address AS ABOUG
Area code and phone no
dame of person interviewed 144 Toxava C Vistoria
Title Experimental A Normania
Mailing address (if different from above) 45 480
Area code and phone no.
1. Site characterization:
a Treatment surface impoundments, chemical, physical, biological
b. Storage - Containers, tanks, Conface impoundments, Containers
c. Disposal - Dand treatment, Dandfill, Dincincration, Dthermal treatment
d.  Use,  reuse,  recycle,  reclaim
2. Does the facility generate hazardous wastes? X Yes Z No
3. Types of hazardous waste produced by Hazardous Waste Number:
FOOS & PRINT LINE RESIDENTS
Are hazardous wastes transported off-site by the facility?   Yes   No
BERKER PRODUCT IS PRINTER OUD PECHELOP.
(PAncestocs & 92)

	LIANCE	1- NON-COMPLIANCE, Z-COMPLIANCE, 3-NOT APPLICABLE, 4-NOT DETERMINED	CHAPTER
. ,	TUS	REQUIREMENT	75.265
<b> </b>		Part A permit application submitted	(a) (2),(:
T×		Identification number •	(b)
1	X	Wastes accepted at facility transported by haulers licensed to transport hazardous waste by the Department	(b) (l)
	X	Waste streams not covered by permit approved by the Department before accept	ance (c)
TX		Chemical and physical analyses repeated as required	(c)(l)
	X	All waste shipments inspected and sampled	(c)(2)
X		Waste analysis plan on-site	(c)(3)
1×		24 hr. surveillance at active portion .	(d) (2)
X		Artificial barrier at active portion	(d)(2)
X		Proper signs posted and legible at a distance of at least 25 ft.	(d)(3)
X		Inspection schedule on-site	(e)(2)
X		Maintenance schedule on-site for equipment or structures which reveal deterioration or malfunction	(e)(4)
X		Immediate remedial action taken where a hazard is imminent or has already occurred	(e)(4)
X		On the job or classroom personnel training program	(£)
		Records retained for each employee at facility of training, job title, and job description	(f)(6)
X		Ignitable or reactive wastes separated from source of ignition or reaction	(g)(1)
\\ \\ \\ \		No smoking signs displayed where there are hazards from ignitable or reactive wastes	(g)(l)
X		Treatment, storage, disposal of ignitable or reactive wastes or mixing of incompatible wastes or materials conducted according to requirements	(g) (2)
×		Facility equipped with internal alarm system capable of providing immediate emergency instruction to personnel	(h) (2)
X		Facility equipped with a device for summoning outside emergency assistance	(h) (2)
T <sub>X</sub>		Facility equipped with fire control, spill control, and decontamination equipment	(h) (2.)
X		Facility equipped with water at adequate volume and pressure to supply fire control equipment	(h) (2)
X		Facility communications or alarm systems, fire control, spill control, and decontamination equipment tested and maintained.	(h) (3)
$\downarrow_{\times}$		Adequate aisle space maintained to allow unobstructed movement of personnel and equipment during emergencies	(h) (6)
IX.		Contingency plan on-site and implemented	(i)(l)
X		Contingency plan describes action taken by personnel in the event of an emergency	(i)(3)
1/		Contingency plan describes arrangements agreed to for outside emergency	

				1- NON-COMPLIANCE, Z-COMPLIANCE, 3-NOT APPLICANE, 4-NOT DETERMINED	
	MPL	rus	)	REQUIREMENT	75.26
	<u>Z</u> 义	2	+	Contingency plan contains an up-to-date list of names, addresses and phone numbers of all persons qualified to act as emergency coordinator	(i)(6)
	$\frac{\triangle}{\times}$		-	Contingency plan contains list of emergency equipment including location, physical description and capabilities of each item	(i.) (7)
	X			Contingency plan contains an evacuation plan if there is a possibility that evacuation could be necessary	(i.) (8)
5	X			One employee designated as the primary emergency coordinator either on the premises or on call.	(i)(11
		X		Facility accepting only PA manifests	(j)
	$\times$			Manifests properly completed and routed within time limits (24 hrs.)	(j)(2)
	χ			Manifest discrepancies resolved or reported within time limits	(j) (10
	-	N.		Written operating record maintained on the premises	(k)
		X		Written operating record contains description and quantity of wastes and method of treatment, storage or disposal	(k) (2)
X		A. S.		Written operating record contains location and quantity of each hazardous waste	(k) (2)
		Х		Written operating record contains results of waste analyses and treatability tests	(k)(2)
		) }		Written operating record contains reports and details of all incidents	(k) (2)
X				Written operating record contains records and results of all inspections	(k) (2)
	T	×		Written operating record contains required monitoring, testing, and analytical data	(k) (2)
.~.	X			Written operating record contains closure and post-closure cost estimates	(k) (2)
	Х			All records retained on premises and available for inspection	(1)
	X			Quarterly reports submitted to the Department	(m)
	X			Emissions, discharges, fires, explosions, and groundwater contamination reported as required	(m) (2)
		X		Groundwater monitoring wells located at approved sites	(n) (2)
1		X		Adequate protection of groundwater monitoring wells	(n) (7)
-		X		Groundwater sampling and analysis plan on the premises	(n) (8)
		X		Groundwater quality assessment and abatement outline on the premises	(n) (14)
-	X			Closure plan on the premises and up-to-date .	(0) (2)
		X		Post-closure plan on the premises and up-to-date	(0)(10)
	X			Annual closure cost estimate on the premises and up-to-date	(p)(2)-
		X		Annual post-closure cost estimate on the premises and up-to-date	(p) (5)-

75.265

1- NON-COMPUANCE, Z-COMPUANCE, 3-NOT APPLICABLE, 4-NOT DETERMINED CHAPTER COMPLIANCE CITATION STATUS REQUIREMENT 1234 Containers managed to prevent leaks and spills (q)(1), Containers are compatible with waste stored. (q)(2)Χ (q)(3)Containers are closed during storage Container storage area inspected weekly for leaks, deterioration, etc. (g)(5)Containers holding ignitable or reactive wastes are set back 15 m (50 ft) (q) (6)from property line. Satisfactory procedures followed for handling incompatible wastes. (q)(7),(q)(9)Incompatible wastes separated or protected from other materials. Act 97 Containers and tanks labeled to identify accurately hazardous waste Section 403(b contained. Precautions taken for tanks holding ignitable, reactive, or incompatible (r)(2)waste or material Tanks managed to prevent leaks, rupture, corrosion, or otherwise failing. (x)(3)X Uncovered tanks operated to ensure at least 60 cm (2 ft) of freeboard. (r)(4)Uncovered tanks equipped with an overflow alarm and an overflow device to a (r)(4)X standby tank with a capacity equal to or exceeding the freeboard requirement Continuously fed tanks equipped with a means to stop the inflow. (r)(5)X Containment structure with a capacity that equals or exceeds the largest above ground tank volume plus a reasonable allowance for precipitation based (r)(6) on local weather conditions and plant operations provided for liquid storage in above ground or partially above ground tanks. Waste analyses and/or trial tests conducted on hazardous wastes substantially (r) (7) different from wastes previously treated or stored; or chemically treat hazardous waste with a substantially different process than any previously used in that tank. This was come and the water out! (r)(8)(Discharge control equipment inspected once each operating day. Monitoring equipment data inspected once each operating day. (r)(8)(Liquid level of tanks inspected once each operating day. (r)(8)(Construction materials of tanks inspected weekly. (r)(8)(Construction materials of discharge confinement structures and area (r)(8)(immediately surrounding inspected weekly. All hazardous waste removed from tanks and related appurtenances at (r)(9)Placement of ignitable or reactive waste only with the Department's approval(r)(10) Covered tanks in which ignitable or reactive waste is treated or stored r)(]]) meets NEDA buffer zone requirements. Precautions taken for handling ignitable, reactive or incompatible waste (r)(12)or material.

Date of inspection 07-19-81 Identification number	10 649024697
Company, Installation name Howard Houngaren Cours	3
County LAWC. Municipality Municipality Municipality	
CONSTRO INNEYSIS NOW ZEE (EE DE	,
PES-CT TUTE CON-T WAZARDOUS LUNGTE.	DETERMINED ARE
TROM THE PHANT DRPZ - ROOM	
PROPER SIGNS HAVE BEEN ROTTED.	4- Chisonia Para
The second se	***
WESTIEN TOOKING Process AND IN THE	
SHOULD BE DEVELOPED AS ACCEDED	en de la companya del companya de la companya del companya de la c
The property of the control of the c	the last control of the control of t
Supplies to write the supplier and the supplier and the supplier of the suppli	administrative en
en e	and the finishesisms of the strong of the st
STATES OF THE ST	and the second s
Commission of the second states of the second state	and the state of t
The support of the contract of	and a superior of the contract
Comparison and the second contract of the sec	. The same of the first the participant participant of the first transfer.
A COMMISSION OF THE COMMISSION	e consequence of the entire entire entire to the consequence of the entire entire entire entire entire entire e
The second design of the secon	andra annua 1828 - Mark market, and departe an under the handledgeneral best of 1871 in the gradient company o
is inspection report is official notification that a representation vironmental Resources, Bureau of Solid Waste Management, inspective findings of this inspection are shown in this report. Any violating the inspection are indicated. Violations may also be discovered sults of laboratory analyses and review of Department records. Naming, confirming any violations indicated herein and listing any	d the above installation. ations which were uncovered ered upon examination of the otification will be forth-
erson Interviewed (signature)	ate / 1 1. 6/8/
	ate. 7 - 1 7 - 2 1

#### UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Region III – 6th & Walnut Sts. Philadelphia, Pa. 19106

SUBJECT: RCRA INSPECTION-HOWMET ALUMINUM CORP (GEN.)

DATE: JAN 12.82

PAD 649024697

DATE: 7.13.81

FROM:

YENER A. SöyLEMER, Environmental Engineer

SUPERFUND/ RERA COMPLIANCE SECTION (3AW 23)

TO:

File

THRU:

WALTER F. LEE, Ph.D., ACTING CHIEF

SUPERFUND/RCRA COMPLIANCE SECTION (3 AW 23)

Robert Collings, Chief

Water & RCRA Enforcement Section(3 Rc 12)

BASED UPON A REVIEW OF THE RCRA INSPECTION REPORT FOR THE

FACILITY REFERENCED ABOVE, I HAVE DETERMINED THAT NO FURTHER

ACTION IS REQUIRED AT THIS TIME.



## HAZARDOUS WASTE INSPECTION REPORT Generators - Part A

JUL 2 : 1981

Generators - Parc A
Div. of Hazardous V
Date of inspection (7-15-8) Time start 1. 30-19. Time finish 2-50 P
Name of inspector Arthur L. David Parket 1 1- a or L received
Company, installation name House Alexander Cost. Man Alexander
Location Park Physics Proceedings of the Authority
County / Municipality / Mangarate / Series
Identification number PAD 649029697
Name of responsible official ///2. (7. 7 / ////)
Title Poncy MCGA
Mailing address // // //re vā
Area code and phone no. 717-77.5 76-76
Name of person interviewed Phys. Journal T. Lennin
Title KNUMENTAL KAGE
Mailing address (if different from above) $\frac{\partial P}{\partial t} = \frac{\partial P}{\partial t} + \frac{\partial P}{\partial t} = $
Area code and phone no.
1. Commont weeks here Wise weekled
1. Current waste handling method:
a. Ø On-site Ø treatment, Ø storage, Ø disposal
b On-site use, recycle, reclaim
c. Ø Off-site Ø treatment, Ø storage, Ø disposal
d. 🖾 Off-site 💹 use, 🖾 reuse, 🖾 recycle, 💆 reclaim
2. Amount of hazardous waste produced:
a kg./po. 2-6 a God of Marietto
b. kg./yr.
3. Types of hazardous waste produced by Hazardous Waste Number:  FROM PARKE FROM BY
4. Are hazardous wastes transported off-site by the generator?  Yes  No
PROCESSON ARKER IN THE P. WINDER

	140:	14.1	er l	1-NON-COMPUNICE, Z-COMPUNICE, 3-NOT APPLICABLE, 4-NOT DETERMINED	CHAPTER
	STAT	JANG US		REQUIREMENT	75.262
	X		-	Identification number .	(c)(1)
	X			Hazardous waste shipments offered only to licensed transporters	(¢)(4)
	X			Authorization received from TSD facility for wastes shipped off-site	(0)
	V			PA manifest used for intrastate shipments	(e)(1)
		X		Disposer state manifest or EPA format manifest used for out-of-state shipments	(e)(1)(
•	X			Manifests filled out properly and completely	(e) (1)
	X		•	Manifests routed properly and within time limits (24 hours)	(e) (2)
-		メ		Proper U.S. DOT shipping containers or packages	(f)(l)
	X			Shipping containers marked and labeled according to U.S. DOT	(f)(l)(
		X		Containers of 110 gal. or less marked with required PA label	(f)(1)(
	X			Placards offered to transporter	(f)(2)
		Χ		Wastes accumulated on-site for less than 90 days Tin switch,	(g)(1)
	X			Wastes stored in proper containers and properly marked and labeled	(g) (1)
	X			Containers managed in accordance with 75.265(g)	(g)(1)
	-	X		Containers clearly marked with accumulation date and visible for inspection	(g)(l)
	X			Records retained at designated location for 20 years	(h)
	X			Quarterly reports submitted to the Department	(i)
	_	X		Exception reporting procedures followed	(j)
ton		×		Hazardous waste disposal plan, if required	(1)
· · · ·		X		Spill reporting procedures followed	(m)(1)
	X			Preparedness, Prevention and Contingency Plan approved and implemented	(m) (5)
		X		Special requirements followed for international shipments	(0)
,_					
	1	1			l

6-43

#### UNITED ST. TES ENVIRONMENTAL PROTECTIC AGENCY

Region III — 6th & Walnut Sts.
Philadelphia, Pa. 19106

SUBJECT:

RCRA Inspection-Howmet Aluminum Corp.

DATE: January 27, 1982

PAD 04 902 9697

FROM:

William L. Walsh, Environmental Protection Assistant

RCRA Compliance And Superfund (3AW23)

WEW

TO:

File

THRU:

Robert L. Collings

Chief, Water & RCRA Enforcement Section (3RC12)

BASED UPON A REVIEW OF THE RORA INSPECTION REPORT FOR THE FACILITY

REFERENCED ABOVE, I HAVE DETERMINED THAT NO FURTHER ACTION IS

REQUIRED AT THIS TIME.

- No.	PHONE CALL DISCUS N FIEL	D TRIP CONFERENCE
RECORD OF COMMUNICATION	OTHER (SPECIFY)	
	(Record of item checked a	above)
TO: Act Dallapiagga PA DER	FROM: Bill Wald	DATE 1/37/82
(717) 787-9697 SUBJECT	RCRA Compliance	TIME 8:20 AM
SUBJECT SUMMARY OF COMMUNICATION 4/8/81 IN		
Ecalled Mr. Da	Mikama toash lin if it	ownet Aluminum
losp. (PAD 04 902\$ 9697)	had corrected the non-cong	pliance problems
1-to- to Holas inspects	a report. He stated that	to the west of hu
boutledge the lacitety has	mel the Angliance Meda -	area to force of
inspection willbe dine is	the near future to fully	vinsure the
failily's corrective actions		
January.		
CONCLUSIONS, ACTION TAKEN OR REQUIRED		
land of the same o		
INFORMATION COPIES		
TO:		

## 

Date of inspection 04-08-81 Time start 10:00 AM Time finish 12:00 pc
Name of inspector DONALD L. KILLIPH AND ARTHUR L. DALLA PIAZZA
Company, installation name HOWMET ASMINIUM COSS MILL FREMETS DIVISION
LOCATION 1480 MANKEIM PINE LANCASTER PG. 17601
County LANCASTER Municipality MANAGER TOWNSAIR
Identification number PADO49029697
Name of responsible official Mf. Guy LANZE
Title PLANT MANAGER
Mailing address STME AS AROYE
Area code and phone no. 717-373 764/
Name of person interviewed Fig. Togeth E. Fischer
Title FANGERIEFING FANGE
Mailing address (if different from above) As Acces
Area code and phone no. 717-373 3691
1. Current waste handling method:
a. 🖾 On-site 🖾 treatment, 🖄 storage, 🔝 disposal
b.  On-site
c. [] Off-site [] treatment, [] storage, [] disposal
d. A Off-site / use, / reuse, A recycle, / reclaim
2. Amount of hazardous waste produced:
a. ~8,000 (F003) (F005)
b1,725,000 19./yr. (1003) V (FOCS)  19./yr. (1000., 1000, 10007, 1000) WAGE ETREPH)
3. Types of bazardous waste produced by Hazardous Waste Number.
FOO3-010 NOT NOTIFY DOOL PRODE PLL CHARMERISTICS WHICH AFRLY TO OME
FOOT-OID NOT NOTIFY DOOL - PALL CHARACTERISTICS CONTICL AFREY TO OME FORTHIS WASTE STREAM. OF HAZORDOUS WASTE, NOTIFED TOO THIS STREAM.  4. Are hazardous wastes transported off-site by the generator?   Yes   NO

04-03-81 PAD049029637

COMPHANCE BIATUS		1- NON-COMPLIANCE, 2-COMPLIANCE, 3-NOT APPLICABLE, 11-NOT DETERMINED  REQUIREMENT	
Z	3 4		75.262
X		Identification number	(c)(1)
X		Hazardous waste shipments offered only to licensed transporters	(c) (4)
X		Authorization received from TSD facility for wastes shipped off-site	(6)
X		PA manifest used for intrastate shipments	(e)(1)
X		Disposer state manifest or EPA format manifest used for out-of-state shipments	(e)(1)(
X		Manifests filled out properly and completely	(e) (1)
X		Manifests routed properly and within time limits (24-h-4178)	(e)(2)
	X	Proper U.S. DOT shipping containers or packages	(f)(1)
	X	Shipping containers marked and labeled according to U.S. DOT	f)(1)(
	X	Containers of 100 gal. or less marked with required PA label	f)(1)(
Х		Placards offered to transporter	(f)(2)
	х	Wastes accumulated on-site for less than 90 days	(g) (1)
	Х	Wastes stored in proper containers and properly marked and labeled	(g) (1)
	X	Containers managed in accordance with 75.265(q)	(g) (l)
	X	Containers clearly marked with accumulation date and visible for inspection	(g) (1)
X		Records retained at designated location for 20 years	(h)
×		Quarterly reports submitted to the Department	(i)
X		Exception reporting procedures followed	(j)
	X	Hazardous waste disposal plan, if required	(1)
X		Spill reporting procedures followed	(m) (1)
X		Preparedness, Prevention and Contingency Plan approved and implemented	(m) (5)
	X	Special requirements followed for international shipments	(0)
			and the second s

# HAZARDOUS WASTE INSPECTION REGITTED Facilities - Part A

Date of inspection 04-08-81 Time start 1:50 9M Time finish 2:30 PM
Name of inspector DONALD L. KILLIAN AND ARTHUR L. DALLA PIAZZA
Company, installation name Howner Gramming CORP MILL PRODUCTS DIVISION
LOCATION 1480 MANHEIM PIKE LANCASTER FA. 17601
County LANCASTER Numicipality MANAEM TOWNSHE
Identification number PAD047037497
Name of responsible official Mg. Guy LANZA
Title PLANT MANAGER
Mailing address AS ABOUE
Area code and phone no. 717-393-9641
Name of person interviewed Mr. Joseffl F. Fischer-
TITLE ENVIRONMENTAL ENGINEER
Mailing address (if different from above) AS ASSIVE
Area code and phone no. AS ABOVE
1. Site characterization:
a. 🌠 Treatment - 🔝 surface impoundments, 🔝 chemical, 🂢 physical, 🗁 biologica
b. X Storage - // containers, X tanks, // surface impoundments, // waste piles
c. [] Disposal - [] land treatment, [] land[11], [] incineration, [] thermal trea
d. 🖾 Use, 💯 reusa, 💯 recycle, 💆 reclaim
2. Does the facility generate hazardous wastes? / Yes / to
3. Types of hazardous white produced by Hazardous Masic Number: FOO3/FOO5 =NO.  DOOL  DOOL  ONE STREMM OF HAZARDOUS WASTE SOLVENTS.
4. Are hazardous wastes transported off-site by the facility? /7 Yes /X/ No

DADO49029697

•	1- NON-COMPLIANCE, Z-COMPLIANCE, ZI-NOT APPLICABLE, Y-NOT DETERMINED						
	STA	IANG TUS 3 4	REQUIREMENT	CHAPTER CITATION 75.265			
	X		Part A permit application substitute	(a) (2),(::			
. 44.0	X		Identification number	(b)			
	-congruent	X	Wastes accepted at racility transported by naulers licensed to transport hazardovs waste by the Department	(b) (1)			
		X	Waste streems not covered by permit approved by the Department before accepta	ince (c)			
		X	Chemical and physical analyses repeated as required	(c)(1)			
		X	All waste shipments inspected and sampled	(c)(3)			
1			Waste analysis plan on-rite	(c)(3)			
		X	24 hr. sucveillance at active postion	<b>4</b> (2)(2)(			
	X	<b></b>	Artificial barrier at active portion	(4)(2):			
1			Proper signs posted and legible is a distance of at least 25 M.	(a) (2)			
	Χ		Inspection schedule comitie	(1) (1)			
· west	Х		Laintenance search to remit to compress of the petro of the result deterioration or valuables.	(0) (4)			
	*		Immediate remedial action takes where a herord is implient or has all may occurred	(e) (4)			
灣	X		On the job or classroom personnel training program	(f)			
	人		Records retained to each employee at facility of training, job tile, and job description	(f)(%),			
	χ		Ignitable or reactive wastes separated from course of innition or reaction	(g) (1)			
	X		No smoking signs displayed where there are hazards from ignitable or reactive wastes	(g) (1)			
2.00.40	X		Treatment, storage, disposal of agnitable or resolive wastes or mixing of incompatible wastes or materials conducted according to requirements	(g)(2)			
	X		Pacility equipped with internal alarm system capable of providing immediate emergency instruction to personnel	(h) (2) /			
	X		Pacility equipped with a device for summoning outside (morgency assistance	(h) (2).			
-	X		Facility equipped with fire control, spill control, and decontamination equipment	(h) (2) (			
. 4.14	×		Facility equipped with water at adequate volume and pressure to supply fire control equipment	(h) (2) (			
yearshoo	X		Facility communications or alarm systems, fire control, spill control, and decontamination equipment tested and maintained.	46) (3)			
	X		Adequate abule space paintained to allow anobal racted assement of personnel and equipment during emergencies	(h) (6)			
	X		Contingency place on-site and inglicemented	(i)(l)			
Computer of	Χ		Contingency plan describes action taken by personnel in the event of an emergency	(i)(3)			
	X		Contingency plan describes arrangements agreed to for outside emergency services such discussed fire described, beguitals, conflactors, etc.	(i)(b)			

1			<u></u> -	1-NON-COMPLIANCE, Z-COMPLIANCE, 3-NOT APPLICABLE, H-NOT DETERMINED	***********		
T K	COMPLIANCE						
	STA	705	)	REQUIREMENT	75.2		
	X			Contingency plan contains an up-to-date list of names, addresses and phone numbers of all persons qualified to act as emergency coordinator.	(i) (6		
	×			Contingency plan contains list of emergency equipment including location, physical description and capabilities of each item	(i) (7		
	X			Contingency plan contains an evacuation plan if there is a possibility that evacuation could be necessary	(i) (8		
	Ž.			One employee designated as the primary emergency coordinator either on the promises or on call.	(i)(		
		X		Facility accepting only PA manifests	(j)		
		X		Manifests properly completed and routed within time limits (24 hrs.)	(j)(Z		
		Х		Manifest discrepancies resolved or reported within time limits	(j) (l		
	X			Written operating record maintained on the premises	(k)		
	×			Written operating record contains description and quantity of wastes and method of treatment, storage or disposal	(k) /2		
	X			Written operating record centains location and quantity of each hazardous waste	(k) (?		
8	X			Written operating record contains results of value analyses and treatability tests	(k) (		
	X			Written operating record contains reports and details of all incidents	(k) (a		
	X			Written operating record contains records and results of all inspections	(k) ().		
		X		Written operating record contains required monitoring, testing, and analytical data	( <b>k)</b> (2		
>	′			Written operating record contains closure and post-element cost estimates	(k) (2		
X	8			All records retained on premises and available for inspection	(1)		
	X			Quarterly reports submitted to the Department	(m)		
	X			Emissions, discharges, fires, explosions, and groundwater contamination reported as required	(m) (2		
		X		Groundwater monitoring wells located at approved sites	(n) (2		
		X		Adequate protection of groundwater monitoring wells	(n) (7		
		X		Groundwater sampling and analysis plan on the premises	(n) (8		
		X		Groundwater quality assessment and abatement outline on the premises	(n) (l		
X				Closure plan on the premises and apoto-date	(0) (2		
		X		Post-closure plan on the premises and up-to-disc	(0) (		
X				Annual closure cost estimate on the promises and up-fordate	(P) (2		
		X		Annual post-clos o cost estimate on the premises and up-to-date	(p) (5		
3	5	•	. 1		1		

Date of inspection 04-08-81 death shows and PAD049029697
ompany, Installation name Hopers I Sulling Core Pluc Prouse Disision
County LANCHETER TOWNS TOWNSON
A WASTE PRINCIPLE BUT SHOWN BUT THE FULL EMENTICE
AS 500N AS 1000 1665, 75 284 (5) (5) 100 110 1100 216115 200410 BE
POSTED AT THE POTINE PARTITION OF THE PACKETY (T.C. THURS) 15265(
A CLESUSE PLAN PAR COST & STIMPTES SHOUD BE DEVELOPED AS
SOON AS POSSIBLE PARTICIPATION FATO THE OPERATION
RECORD. 75.265(K)(ZYV);75.265(0);75.265(p).
IT IS RECOMMENDED THAT THE RUCES AND RECULATIONS
BE REVIEWED IN OFFER TO BETTER HINTERSTHAND THOSE ITEMS WHICH
NEED TO BE ACOPESSED, AS SOND AS POSSIBLE.
This inspection report is official notification that a representative of the Department of Invironmental Resources, Bureau of Solid Mante Management, inspected the above installation. The findings of this inspection are shown is this report. Any violations which were uncovered Juring the inspection are indicated. Violations may also be discovered upon examination of the Results of laboratory analyses and review of Department records. Motification will be forth-toming, confirming any violations indicated by in and that incords.
Parson Interviewed (cignature) Joseph Fairle 100 8 Apr. 31
Laspeoter (signature) Donald L'Killian 4/2/8/
Center I Dallohayen



## COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL RESOURCES

BUREAU OF WASTE MANAGEMENT One Ararat Boulevard Harrisburg, Pennsylvania 17110 (717) 657-4588

SEP. 25 1987

DER
SOLID WASTE MANAGEMENT

CERTIFIED MAIL NO. P-517 982610

OCT 19 1987

Alumax Aluminum Corporation Mill Products Box 3167, 1480 Manheim Pike Lancaster, PA 17604

HARRISBURG REGION

Attn: Mr. Stephen C. Kirchner

Re: Non-Compliance Hazardous Waste Activity
Alumax Aluminum Corporation
I.D. No. PADO49039697
Manheim Township, Lancaster County

#### Gentlemen:

Pursuant to the meeting on July 21, 1987, I am forwarding three (3) copies of a Letter-Agreement in settlement of Alumax Aluminum Corporation's (hereinafter "Alumax") violations of the Pennsylvania Solid Waste Management Act, the Act of July 7, 1980, P.L. 380, 35 P.S. §6018.101 et seq., (hereinafter "SWMA"), and the Rules and Regulations promulgated thereunder which occurred on November 6, 1986 at Alumax in Manheim Township, Lancaster County, Pennsylvania.

Please have two (2) authorized officials of Alumax sign all three (3) copies and return them to this office within ten (10) days of your receipt thereof. You will receive an executed copy for your records after the document is signed on behalf of the Department of Environmental Resources (hereinafter "Department").

The facts of the matter and the terms of settlement are as follows:

- 1. Alumax-is a Delaware corporation registered to do business in the Commonwealth of Pennsylvania.
- 2. Alumax owns and operates an aluminum mill products facility located at 1480 Manheim Pike, Box 3167, Manheim Township, Lancaster County, Pennsylvania 17604 (Manheim Township Facility").

DER SOLID WASTE MANAGEMENT

NOV 0 5 1987

HARRISBURG REGION

- 3. Alumax generates hazardous waste at its Manheim Township Facility and is identified by the Generator's U.S. EPA I.D. No. PADO49029697.
- 4. On November 6, 1986, Alumax offered a shipment of hazardous waste for transportation, from the Manheim Township Facility, without ensuring that the required information on all copies of Manifest MDC0034658 was capable of being read, in violation of 25 Pa. Code §75.262(e)(17).
- 5. The action described in Paragraph 4 above constitutes unlawful conduct on the part of Alumax pursuant to Sections 403(a), 403(b)(5), 610(4), and 610(9) of the SWMA, 35 P.S. §§6018.403(a), 6018.403(b)(5), 6018,610(4) and 6018.610(9); and constitutes a public nuisance pursuant to Section 601 of the SWMA, 35 P.S. §6018.601.
- 6. In settlement of all claims for monetary penalties assessable pursuant to Section 605 of the SWMA, 35 P.S. §6018.605, for the violations described in Paragraphs 1 through 5 above, Alumax agrees to pay to the "Commonwealth of Pennsylvania, Solid Waste Abatement Fund" the sum of Five Hundered Dollars (\$500.00). This sum is a figure for settlement purposes only as set forth herein, and shall be due and payable upon execution of this Letter-Agreement. Said Five Hundred Dollar (\$500.00) payment shall be submitted to the Department together with the signed copies of this Letter-Agreement and shall be in the form of a certified check or the like, made payable to the "Commonwealth of Pennsylvania Solid Waste Abatement Fund" and shall be forwarded to Michael R. Steiner, Regional Solid Waste Manager, Bureau of Waste Management, Department of Environmental Resources, One Ararat Boulevard, Harrisburg, PA 17110.
- 7. In consideration of the timely receipt of the above payment and the execution of this Letter-Agreement by Alumax, the Department agrees not to initiate any action pursuant to Section 605 of the SWMA, supra, against for violations of the SWMA which occurred on November 6, 1986 as described in Paragraphs 1 through 5 above; provided, however, that nothing in this Letter-Agreement shall be construed as to relieve Alumax from any future liability for environmental damage which may have resulted from the activities described herein.

8. Nothing contained in this Letter-Agreement shall be construed to relieve or limit the obligations of Alumax to comply with the terms and conditions of any permit existing or hereafter issued by the Department to Alumax or to limit any civil or criminal liability of Alumax for violations of the law except as specifically set forth in paragraphs 6 and 7 above.

Sincerely,

Michael R. Steiner

Regional Solid Waste Manager Harrisburg Regional Office

MRS: jvl

The facts and terms of this Letter-Agreement are hereby consented and agreed to:

FOR COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL RESOURCES:

FOR ALUMAX ALUMINUM CORPORATION:

Michael R. Steiner

Regional Solid Waste Manager Harrisburg Regional Office

Vice President

APPROVED AS TO LEGALITY AND FORM:

Mary Young

Assistant Counsel Office of Chief Counsel

Execution Date (Dated by last signatory hereto)

AFFIX CORPORATE SEAL

### UNITED STATES ENVIRONMENTAL PROTECTION AGENCY **REGION III**

841 Chestnut Building Philadelphia, Pennsylvania 19107

SUBJECT: RCRA Inspection ALUMAK ALUMINUM CORP.

DATE: 4/15/87

PAD 04 902 9697

FROM:

Joseph S. Arena -18A

Environmental Scientist (3HW11)

TO:

File

Thru:

Peter W. Schaul, Chaef

RCRA Enforcement Section (3HW11)

BASED UPON A REVIEW OF THE RCRA INSPECTION REPORT FOR THE FACILITY REFERENCED ABOVE, I HAVE DETERMINED THAT NO FURTHER ACTION IS REQUIRED AT THIS TIME.

#### UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Region III — 6th & Walnut Sts. Philadelphia, Pa. 19106

SUBJECT: RCRA Inspection-

Howmet Aluminum Corp PAD049029697

DATE: April 27, 1983

William L. Walsh, Environmental Protection Aid FROM Superfund/RCRA Compliance Section (3AW23)

TO: File

Walter F. Lee, Chief Thru:Superfund/RCRA Compliance Section (3AW23)

BASED UPON A REVIEW OF THE RCRA INSPECTION REPORT FOR THE FACILITY REFERENCED ABOVE, I HAVE DETERMINED THAT NO FURTHER ACTION IS REQUIRED AT THIS TIME.

4/22/82

## UNITED ST. TES ENVIRONMENTAL PROTECTIC AGENCY Region III - 6th 2 Weinut Sts.

Philodelphia, Pa. 19106

SUBJECT: RORA Inspection-Howmet Aluminum Corp.

DATE: January 27, 1982

PAD 04 902 9697

FROM:

William L. Walsh, Environmental Protection Assistant

RCRA Compliance And Superfund (SAM23)

1000

TO:

File

THRU:

Robert L. Collings

Chief, Water & RCRA Enforcement Section (3RC12)

BASED UPON A REVIEW OF THE RORA INSPECTION REPORT FOR THE FACILITY

PEFERENCED ABOVE, I HAVE DETERMINED THAT NO FURTHER ACTION IS

REQUIRED AT THIS TIME.

1/27/82

### UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Region III – 6th & Walnut Sts. Philadelphia, Pa. 19106

SUBJECT: RCRA INSPECTION-HOWMET ALUMINUM CORP (GEN.)

DATE: JAN 12.82

PAD 649024697

DATE: 7.13.81

FROM:

YEHER A. SöyLEMER, Environmental Engineer

SUPERFUND/ REA COMPLIANCE SECTION (3AW 23)

TO:

File

THRU:

WALTER F. LEE, Ph.D., ACTING CHIEF

SUPERFUND/ RCRA COMPLIANCE SECTION (3 AW 23)

Robert Collings, Chief

Water & RCRA Inforcement Section(3 Rc 12)

BASED UPON A REVIEW OF THE RCRA INSPECTION REPORT FOR THE

FACILITY REFERENCED ABOVE, I HAVE DETERMINED THAT NO FURTHER

ACTION IS REQUIRED AT THIS TIME.

7/13/8/